

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/07/2020

Submitted Date:

04/08/2020

Document Number:

689704531

FIELD INSPECTION FORM

Loc ID 335164 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: PO BOX 370
City: PARACHUTE State: CO Zip: 81635

Findings:

- 13 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Byers, Jim		jbyers@blm.gov	
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211055	WELL	PR	11/23/2003	OW	045-06813	FEDERAL GR 32-34	PR
263070	WELL	PR	12/15/2002	GW	045-08102	FEDERAL GM 332-34	PR
263071	WELL	PR	03/14/2002	GW	045-08103	FEDERAL GM 42-34	PR
263072	WELL	PR	12/16/2002	GW	045-08104	FEDERAL GM 342-34	PR
278719	WELL	PR	04/18/2006	GW	045-10921	FEDERAL GM 442-34	PR
278720	WELL	PR	04/20/2006	GW	045-10922	FEDERAL GM 542-34	PR
278721	WELL	PR	04/20/2006	GW	045-10923	FEDERAL GM 532-34	PR
278722	WELL	PR	04/20/2006	GW	045-10924	FEDERAL GM 432-34	PR

General Comment:

This is a summary of inspection report.
On Tuesday 04/07/2020 at approximately 1500 hours, I, Inspector Mike Longworth, conducted a field inspection at Terra Rocky Mountain LLC FEDERAL-66S96W 34SWNE, at Location # 335164 in Garfield County, Colorado
During this inspection the following possible compliance issues were observed:
Tubing tool in ditch across from separators. Unused tubing behind separators.
Comply with Rule 603.f .
C.A. Date 05/08/2020
Unmarked deadmen.
Mark guy line anchors per Rule 1003.a.
C.A. Date 04/24/2020
Erosion of access road just before top of location.
Maintain and repair access road.
C.A. Date 05/08/2020
A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location			
Lease Road:			
Type	Access		
comment:	Erosion of access road just before top of location. Noted on previous Inspection (08/23/2018 insp # 689701748)		
Corrective Action	Maintain and repair access road.	Date:	05/08/2020
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Tubing tool in ditch across from separators. Unused tubing behind separators.		
Corrective Action:	Comply with Rule 603.f .	Date:	05/08/2020
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No _____			
Comment:	_____		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			

Corrective Action:		Date:	
Equipment:			corrective date
Type: Deadman # & Marked	# 3		
Comment:	2 unmarked deadmen and 1 deadman marker broken off near base.		
Corrective Action:	Mark guy line anchors per Rule 1003.a.	Date:	04/24/2020

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	80 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	OTHER	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	250 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	211055	Type:	WELL	API Number:	045-06813	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well							Date:	
Corrective Action:								Date:	
Facility ID:	263070	Type:	WELL	API Number:	045-08102	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well							Date:	
Corrective Action:								Date:	
Facility ID:	263071	Type:	WELL	API Number:	045-08103	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well							Date:	
Corrective Action:								Date:	
Facility ID:	263072	Type:	WELL	API Number:	045-08104	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well							Date:	
Corrective Action:								Date:	
Facility ID:	278719	Type:	WELL	API Number:	045-10921	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well							Date:	
Corrective Action:								Date:	
Facility ID:	278720	Type:	WELL	API Number:	045-10922	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well							Date:	
Corrective Action:								Date:	
Facility ID:	278721	Type:	WELL	API Number:	045-10923	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well							Date:	
Corrective Action:								Date:	
Facility ID:	278722	Type:	WELL	API Number:	045-10924	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well							Date:	
Corrective Action:								Date:	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689704538	Inspection 689704531 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5118010