

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/09/2020

Submitted Date:

04/09/2020

Document Number:

699800885

FIELD INSPECTION FORM
 Loc ID 334555 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1401 SEVENTEENTH STREET #1401

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

9 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------|-------|---------------------------------------|---------|
| Kellerby, Shaun | | shaun.kellerby@state.co.us | |
| , Laramie | | cogccnotifications@laramie-energy.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 259487 | WELL | PR | 02/15/2003 | GW | 077-08728 | BUZZARD CREEK 14-1 | PR |
| 262734 | WELL | PR | 12/01/2019 | GW | 077-08753 | BUZZARD CREEK 14-8 | PR |

General Comment:**COGCC Inspection Report Summary**

On Thursday 4/9/20 at approximately 14:00 hours, I, Inspector Corey De Paolo, Conducted an on-site inspection at LARAMIE ENERGY LLC Buzzard Creek /14B Pad, Location #334555 in Mesa County Colorado.

While there, I observed normal production operations.

During this inspection the following possible compliance issues were observed: Both 500 gallon methanol tanks missing operator name and contact number. See photo #0942 with a corrective action date of 6/9/20. Multiple deadman not marked. See photo #0943 and #0949 with a corrective action date of 4/23/20. Multiple holes in tank containment Liner. See photo #0945, #0946 and #0947 with a corrective action date of 4/29/20.

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.
This is a summary of inspection report.

| Location | | | | |
|--|---|--------|--|------------------|
| Lease Road: | | | | |
| Type | Access | | | |
| comment: | | | | |
| Corrective Action | L | | | Date: |
| Overall Good: <input checked="" type="checkbox"/> | | | | |
| Signs/Marker: | | | | |
| Type | WELLHEAD | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Type | TANK LABELS/PLACARDS | | | |
| Comment: | Both 500 gallon methanol tanks missing operator name and contact number. See photo #0942 | | | |
| Corrective Action: | All tanks with a capacity of ten (10) barrels or greater shall be labeled with Name of operator, Operator's emergency contact telephone number. Properly label tanks. | | | Date: 06/09/2020 |
| Type | BATTERY | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Emergency Contact Number: | | | | |
| Comment: | 911 | | | |
| Corrective Action: | | | | Date: _____ |
| Good Housekeeping: | | | | |
| Type | DEBRIS | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Overall Good: <input checked="" type="checkbox"/> | | | | |
| Spills: | | | | |
| Type | Area | Volume | | |
| In Containment: No | | | | |
| Comment: _____ | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |
| Fencing/: | | | | |
| Type | LOCATION | | | |
| Comment: | Barbed wire fence around location | | | |
| Corrective Action: | | | | Date: |
| Type | WELLHEAD | | | |
| Comment: | Livestock panels | | | |
| Corrective Action: | | | | Date: |
| Equipment: | | | | |
| Type: Bird Protectors | # 4 | | | corrective date |
| Comment: | | | | |

| | | | |
|---------------------------------|---|-------|------------------|
| Corrective Action: | | Date: | |
| Type: Deadman # & Marked | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Deadman # & Marked | # 2 | | |
| Comment: | Multiple deadman not marked. See photo #0943 and #0949 | | |
| Corrective Action: | All guy line anchors left buried for future use shall be identified by a marker of bright color not less than four (4) feet in height. Properly mark deadman. | | Date: 04/23/2020 |
| Type: Vertical Heated Separator | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CONDENSATE | 2 | 300 BBLs | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|--|---------------------|---------------------|------------------|
| Metal | Adequate | Walls Insufficient | Base Sufficient | Inadequate |
| Comment: | Multiple holes in tank containment Liner. See photo #0945, #0946 and #0947 | | | |
| Corrective Action: | Secondary containment devices shall be sufficiently impervious to contain any spilled or released material. Repair tank containment liner. | | | Date: 04/29/2020 |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

Inspected FacilitiesFacility ID: 259487 Type: WELL API Number: 077-08728 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Facility ID: 262734 Type: WELL API Number: 077-08753 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | | | | | | |
| | | Gravel | | | | |
| Gravel | | | | | | |
| | | Culverts | | | | |
| Berms | | | | | | |
| | | Ditches | | | | |
| | | Compaction | | | | |
| Ditches | | | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-----------------------------|---|
| 699800886 | Photos for Insp. #699800885 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5120203 |