

Inspection Photos  
Operator: Catamount Energy  
API#: 007-06122  
Date: 5/15/2020



Photo 1. View of the project area from the southern corner facing center.



Photo 2. View of the southeastern project area from the southern corner facing northeastward. Revegetation is progressing with mixed wheatgrasses and rubber rabbitbrush.



Photo 3. View of erosional channeling (approximately 1 foot wide and deep), within the northern project area. Hard hat in place for scale.



Photo 4. View of reference area vegetation comprised of mixed pinyon and juniper woodland, with gamble oak and mosaic, with grasses such as western wheatgrass and forbs such as *Penstemon* spp. in the understory.