

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/07/2020

Submitted Date:

05/18/2020

Document Number:

688800733**FIELD INSPECTION FORM**Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
Hughes, Jim \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 1199 MAIN AVENUE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
- 
- ☒
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**14 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Heil, John		john.heil@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	<a href="#">SW Inspection Reports</a>
Inspections, All		SanJuanCOGCC@bp.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
268987	WELL	PR	01/01/2018	GW	067-08810	MCCAW C 2	EI
476264	SPILL OR RELEASE	AC			-	McCaw C 2	EI

**General Comment:**

On May 7, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Spill/Release Point ID #476264. For the most recent field inspection report of the McCaw C #2, please refer to document #693900133. For more information regarding Spill/Release Point ID #476264, please refer to document #402394317.

## Location

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Free standing sign near location entrance.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Posted on location signs.		
Corrective Action:		Date:	

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		
Produced Water	Separator	>= 5 bbls		
Comment:	Please refer to Initial Form 19 Document #402394317.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.			Date: 06/18/2020

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	Stock panel fencing around separator, telemetry equipment, meter run, and PBV.		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Stock panel fencing.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 1		
Comment:	Operating at the time of this inspection.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Type: Prime Mover	# 1	
Comment:	Natural gas powered.	
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment:	Telemetry equipment.	
Corrective Action:		Date:
Type: Flow Line	# 1	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		37.161331,-107.728131
Comment:	Paint is peeling off of PBV.				
Corrective Action:					Date:

**Paint**

Condition	Inadequate
Other (Content)	
Other (Capacity)	95 bbl.
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	268987	Type:	WELL	API Number:	067-08810	Status:	PR	Insp. Status:	EI
Facility ID:	476264	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Secondary containment for lube oil container.
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On May 7, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Spill/Release Point ID #476264. For the most recent field inspection report of the McCaw C #2, please refer to document #693900133. For more information regarding Spill/Release Point ID #476264, please refer to document #402394317. During this inspection, stained gravel was observed near the separator.	hughesjo	05/18/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402401150	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5153396">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5153396</a>
688800734	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5153388">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5153388</a>