

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/15/2020

Submitted Date:

05/18/2020

Document Number:

700300015

FIELD INSPECTION FORM

Loc ID: 313550 Inspector Name: LABOWSKIE, STEVE On-Site Inspection: 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 8725

Name of Operator: BLACK RESOURCES, INC

Address: 320 MUSTANG TRAIL

City: GRANBURY State: TX Zip: 76049

Findings:

9 Number of Comments

2 Number of Corrective Actions

Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Black, Bill		blackmustang.biz@gmail.com	
Burger, Craig		craig.burger@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
224454	WELL	TA	06/14/1990	GW	083-06519	STATE 36-11	TA

General Comment:

Inspection for witness of 5-year mechanical integrity test as required by Rule 326. Upon arrival at 9:30 AM, operator had just pulled up to well with pump truck, well had not been pre-tested as prescribed in operator guidance and procedure. Inspector asked operator representative if any H2S was present in the gas, he replied that yes there was but did not know how much. Inspector then drove off site and requested gas analysis from operator per Rule 206. Gas analysis was e-mailed to COGCC and Montezuma Co. LGD on 5/19/20 and indicated 250 ppm H2S.

No H2S monitors or equipment, signs, wind indicators, JSAs were present, no pre-job safety meeting held. Operator representative had dog on location who was a distraction and was jumping on inspector.

No sundry notice for H2S or gas analysis found in well file at time of test.

Because gas has greater than 100 ppm H2S, per Rule 607 and BLM Onshore Order No. 6 a "Danger H2S" is required no less than 200' from entrance to location and no more than 500' from location and at wellhead. At least one brightly colored conspicuous wind indicator is required. 2 points of exit are required for operations.

Operator must file a form 4 sundry notice with public protection plan or an explanation of why a public protection plan is not required. Note: need for public protection plan is determined by conducting radius of exposure calculations or equivalent per methods outline in BLM Onshore Order No. 6.

Location			
Lease Road:			
Type	Access		
comment:	slightly overgrown with brush		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	older sign at entrance to location has different 24 hour operatro contact number, old number should be removed to prevent confusion.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	only 1 rig anchor observed, anchor painted yellow although not adeqautely marked		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	Dead dry weeds around wellhead		
Corrective Action:	remove dead vegetation debris	Date:	06/18/2020
Type	WEEDS		
Comment:	Thistle debris from last growing season present		
Corrective Action:	remove debris and monitor/control regrowth	Date:	06/18/2020
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	LOCATION		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Equipment:			
Type:	Ancillary equipment	# 1	corrective date
Comment:	well head		

Corrective Action:		Date:	
Type: Deadman # & Marked	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:	bradenhead open during test to monitor		
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 224454 Type: WELL API Number: 083-06519 Status: TA Insp. Status: TA**Idle Well**Purpose: Shut In Temporarily Abandoned Reminder: _____Comment: Witness 5 year MIT - Intial tubing = 39 psi, initial casoing = 225 psi, puff of pressure on bradenhead when valve opened. Slowly pressured casing to 610 psi (over 30 mins, stopped in middle to wrok on pump), added aprox. 15 bbls from truck.

No change on tubing pressure, 612 psi final casing pressure, no flow detected while bradenhead open during test, operator charted test.

Corrective Action: _____

Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402401248	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5153503
700300016	tubing gauge at start	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5153493
700300017	casing gauge at start	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5153494
700300018	dead dry vegetation around wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5153495
700300019	inadequately marked rig anchor	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5153496
700300020	thistles from last season	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5153497