

Location Name: – Ward and Son Operating - Loc ID 317166

Inspection Date: 06/23/2020



Photo # 1 –



Location Name: – Ward and Son Operating - Loc ID 317166
Inspection Date: 06/23/2020



Photo # 2 –

Location Name: – Ward and Son Operating - Loc ID 317166
Inspection Date: 06/23/2020



Photo # 3 –

Location Name: – Ward and Son Operating - Loc ID 317166
Inspection Date: 06/23/2020



Photo # 4 –

Location Name: – Ward and Son Operating - Loc ID 317166

Inspection Date: 06/23/2020



Photo # 5 – View north across Pit ID 117639 subject of Spill ID 476164



Location Name: – Ward and Son Operating - Loc ID 317166
Inspection Date: 06/23/2020



Photo # 6 – View south across Pit ID 117639 subject of Spill ID 476164



Location Name: – Ward and Son Operating - Loc ID 317166

Inspection Date: 06/23/2020



Photo # 7 – Pit ID 117639 subject of Spill ID 476164. Discontinuous oil stains in pit wall



Location Name: – Ward and Son Operating - Loc ID 317166

Inspection Date: 06/23/2020



Photo # 8 – Pit ID 117639 subject of Spill ID 476164. Oil stained soil in pit wall



Location Name: – Ward and Son Operating - Loc ID 317166

Inspection Date: 06/23/2020



Photo # 9 – View east across Pit ID 117639 subject of Spill ID 476164. Discontinuous oil stained soil in eastern pit wall



Location Name: – Ward and Son Operating - Loc ID 317166
Inspection Date: 06/23/2020



Photo # 10 – View south along BMP installed on the west side of Pit ID 117639 subject of Spill ID 476164.



Location Name: – Ward and Son Operating - Loc ID 317166

Inspection Date: 06/23/2020



Photo # 10 – View east across southern side of Pit ID 117639 subject of Spill ID 476164.

