

Inspection Photos

Operator: Paradox Upstream
API: 113-06235
Date: 7/16/2020



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Revegetation is progressing in a grazed condition with grasses and shrubs such as western wheatgrass, Indian ricegrass, and rubber rabbitbrush.



Photo 3. View of the southern project area from the southeastern corner facing westward.




Photo 4. View of musk thistles within the southeastern project area. Approximately 200 individuals observed.



Photo 5. View of reference area comprised of post-burn vegetation community with young pinyon and juniper trees, rubber rabbitbrush, sand dropseed, and western wheatgrass.