

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

08/20/2020

Submitted Date:

08/20/2020

Document Number:

699302395**FIELD INSPECTION FORM**
 Loc ID 331236 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259558	WELL	TA	02/01/2017	GW	123-20353	HSR-DEEPE 3-22A	TA
435178	WELL	PR	04/01/2019	OW	123-38496	DEEPE 14N-27HZ	PR
435179	WELL	PR	04/01/2019	OW	123-38497	DEEPE 36C-27HZ	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	adequate x 3		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Ag fence x 3		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 3		
Comment:	appear to be plumbed to surface		
Corrective Action:		Date:	
Type: Ancillary equipment	# 5		
Comment:	Automation, corossion inhibitor and tranformer		
Corrective Action:		Date:	
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 259558 Type: WELL API Number: 123-20353 Status: TA Insp. Status: TA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: TA since 2-1-2017, Form 04 (TA) Doc # 402425726 submitted on 6-18-2020 and is in process.

Corrective Action: _____ Date: _____

Facility ID: 435178 Type: WELL API Number: 123-38496 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

Facility ID: 435179 Type: WELL API Number: 123-38497 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday 8/20/2020 at approximately 1020 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Kerr McGee location:</p> <p style="text-align: center;">Deepe 14N-27HZ at Location</p> <p>#331236 in Weld County Colorado. While there, I observed a Multi well pad. HSR-Deep 3-22A TA since 2-1-2017, Form 04 (TA) Doc # 402425726 submitted on 6-18-2020 and is in process. The Deep 14N-27HZ & 36N-27HZ are PR. During this inspection no compliance issues were observed: See attached photos. Location is dry, weather is clear. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	revasr	08/20/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699302396	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5229174