

Inspection Photos  
Location Name: HILL RANCH 36-13  
API#: 05-071-08253  
INSP. #: 695103248



Colorado Oil & Gas Conservation Commission  
37.03499, -104.95365, 2539.0m, 343°  
2020/08/24 14:18:10

PHOTO 1: LOCATION



Colorado Oil & Gas Conservation Commission  
37.03505, -104.95381, 2525.0m, 247°  
2020/08/24 14:35:57

PHOTO 2: WELL SIGN

Inspection Photos  
Location Name: HILL RANCH 36-13  
API#: 05-071-08253  
INSP. #: 695103248



**PHOTO 3: AREA OF IMPACTED SOIL AROUND DRIVEHEAD ENGINE SKID. Conduct maintenance on equipment, cleanup IMPACTED SOIL and review self inspection processes. CA DATE 11-24-20.**

**PHOTO 4: ANOTHER IMAGE OF IMPACTED SOIL AROUND ENGINE SKID.**

Inspection Photos  
Location Name: HILL RANCH 36-13  
API#: 05-071-08253  
INSP. #: 695103248



**PHOTO 5: OILY FLUID STORED IN ENGINE SKID.**

**Comply with general provisions of the oil and gas act for wildlife protection. CA DATE 8-29-20.**