

# Inspection Photos

8/31/2020

Operator: GUNNISON ENERGY LLC - 10515

Location ID: 324457

Gunnison County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: GUNNISON ENERGY LLC - 10515  
Location ID: 324457



**Photo 1:** Photo taken from the access road, facing northeast. Photo shows Location remains out of compliance with 1004 rules and corrective actions; Final reclamation of the Location has not been conducted.





## Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 324457



**Photo 2:** Photo taken from the west end of the Location, facing east. Photo shows Location remains out of compliance with 1004 rules and corrective actions; Final reclamation of the Location has not been conducted.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 324457



**Photo 3:** Photo taken from the west end of the Location, facing east. Photo shows Location remains out of compliance with 1004 rules and corrective actions; Final reclamation of the Location has not been conducted.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 324457



**Photo 4:** Photo taken from the Location, facing west. Photo shows Location remains out of compliance with 1004 rules and corrective actions; Final reclamation of the Location has not been conducted.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Inspection Photos  
Operator Name: GUNNISON ENERGY LLC - 10515  
Location ID: 324457



**Photo 5:** Photo shows areas of the Location where gravel has not been removed.





## Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 324457



**Photo 6:** Photo taken from the northwest end of the Location. Photo shows anchor has not been removed.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 324457



**Photo 7:** Photo taken from the access road. Evidence of weed management was observed, however the time appears to have been insufficient; Photo shows Musk thistle plat with viable seed head. Ongoing noxious weed management is required.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 324457



**Photo 8:** Photo shows musk thistle in the process of dying back.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources