

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/12/2020

Submitted Date:

10/13/2020

Document Number:

696103833

FIELD INSPECTION FORMLoc ID 435903 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10110

Name of Operator: GREAT WESTERN OPERATING COMPANY LLC

Address: 1001 17TH STREET #2000

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

22 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
,		cogccinspections@gwogco.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
435902	WELL	PR	08/14/2015	OW	123-38838	Bruegman South EG 34-022HN	PR
435906	WELL	PR	08/06/2014	OW	123-38841	Bruegman South EG 34-024HC	PR
435907	WELL	PR	05/01/2017	OW	123-38842	Bruegman South EG 34-021HN	PR

General Comment:

This is a WELL / BATTERY inspection.

Well(s): 3: Producing | PR.

Battery: Active.

Location				
Lease Road:				
Type	Access			
comment:	Adequate			
Corrective Action	L		Date:	
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	TANK LABELS/PLACARDS			
Comment:	Crude oil tank contents / capacity labeling is faded and barely legible. Consider updating contents / capacity labeling.			
Corrective Action:			Date:	
Type	CONTAINERS			
Comment:	Methanol, Paraffin Control, Emulsion Breaker, Motor Oil.			
Corrective Action:			Date:	
Type	WELLHEAD			
Comment:	3: Wellsites.			
Corrective Action:			Date:	
Type	BATTERY			
Comment:	No Battery sign with company & well name(s) posted at battery site. Refer to Rule 210.b. Post Company, & Well name(s) at battery site. Comply w/ Rule 210.b. Corrective Action date: 12/14/2020. See photo #4.			
Corrective Action:	Post Company, & Well name(s) at battery site. Comply w/ Rule 210.b. See photo #4.		Date:	12/14/2020
Emergency Contact Number:				
Comment:	No Emergency contact number posted at battery site. Refer to Rule 210.b. Post Emergency contact number at battery site. Comply w/ Rule 210.b. Corrective Action date: 11/12/2020. See photo #4.			
Corrective Action:	Post Emergency contact number at battery site. Comply w/ Rule 210.b. See photo #4.			Date: 11/12/2020
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	3: Wellsites. Iron panel.			
Corrective Action:			Date:	
Type	SEPARATOR			

Comment: Surrounded by metal berms.			
Corrective Action:		Date:	
Equipment:			corrective date
Type: Ancillary equipment	# 13		
Comment: At Battery: 1: ECD scrubber. 2: Sound mitigation walls. 1: Motor oil tank w/ drip containment. Placarded. 1: Emulsion breaker drum w/ drip containment. Placarded. 1: Emulsion breaker 5-gal. can. Placarded. 2: Methanol pumps, tanks w/ drip containment. Placarded. 1: Methanol tank w/ drip containment. Placarded. At Wellsites: 1: Methanol pump, tank w/ drip containment. Placarded. 3: Paraffin control pumps, tanks w/ drip containment. Placarded.			
Corrective Action:		Date:	
Type: Emission Control Device	# 3		
Comment: Controls crude oil tanks VOCs. Pilots: ON.			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 4		
Comment: 3: Allocation. Calibration card indicates calibration within last year. Last calibration: 07/24/2020. Meter is active. 1: Master Sales. Calibration card indicates calibration within last year. Last calibration: 09/30/2020. Meter is active.			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 3		
Comment: 3: Wellsites.			
Corrective Action:		Date:	
Type: Compressor	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 3		
Comment: 3: Wellsites. Appears plumbed to surface.			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	OTHER	PBV FIBERGLASS		,	
Comment:						
Corrective Action:						Date:

Paint

Condition					
Other (Content)					
Other (Capacity)	150 Bbls.				
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:		Shares berms w/ crude oil tanks.		
Corrective Action:		Date:		

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	6	OTHER	STEEL AST		40.522869,-104.545215	
Comment:		Equalizer lines connect crude oil tanks.				
Corrective Action:		Date:				

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)	533 Bbls.				
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:		Shares berms w/ produced H2O tanks.		
Corrective Action:		Date:		

Venting:

Yes/No	NO		
Comment:			
Corrective Action:	Date:		

Flaring:

Type			
Comment:			
Corrective Action:	Date:		

Inspected Facilities									
Facility ID:	435902	Type:	WELL	API Number:	123-38838	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing PR.								
Corrective Action:						Date:			
Facility ID:	435906	Type:	WELL	API Number:	123-38841	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing PR.								
Corrective Action:						Date:			
Facility ID:	435907	Type:	WELL	API Number:	123-38842	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing PR.								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On MON 10/12/2020 at approximately 13:37 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: GREAT WESTERN OPERATING COMPANY LLC Location Name: Bruegman South EG Pad /34-021HN Location ID: 435903 Well Names: Bruegman South EG 34-021HN, Bruegman South EG 34-022HN, Bruegman South EG 34-024HC API: 05-123-38842, 05-123-38838, 05-123-38841 Location County: Weld County, Colorado Weather: Mostly clear, dry.</p> <p>While there, I observed: Well(s): 3: Producing PR. Battery: Active.</p> <p>During this inspection the following possible compliance issues were observed: 1.) No Emergency contact number posted at battery site. Refer to Rule 210.b. Post Emergency contact number at battery site. Comply w/ Rule 210.b. Corrective Action date: 11/12/2020. See photo #4.</p> <p>2.) No Battery sign with company & well name(s) posted at battery site. Refer to Rule 210.b. Post Company, & Well name(s) at battery site. Comply w/ Rule 210.b. Corrective Action date: 12/14/2020. See photo #4.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	evinsb	10/13/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696103834	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5268418