

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/20/2020

Submitted Date:

10/20/2020

Document Number:

701100614

FIELD INSPECTION FORM

Loc ID 421108	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: 10091 Name of Operator: BERRY PETROLEUM COMPANY LLC Address: 5201 TRUXTUN AVENUE #100 City: BAKERSFIELD State: CA Zip: 90339				Findings: 12 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Armstrong, Jon		jarmstrong@bry.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Wilbourn, Don		dwilbourn@bry.com	
Johnson, Derek	970-285-2200	djohnson@bry.com	Dist. Superintendent

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293396	WELL	PR	07/29/2015	OW	045-14956	SCHOOL HOUSE POINT OM01B B21 696	PR
293397	WELL	PR	01/19/2016	OW	045-14957	SCHOOL HOUSE POINT OM01C B21 696	PR
421132	WELL	PR	01/20/2016	OW	045-20304	SCHOOL HOUSE POINT OM08C B21 696	PR
421134	WELL	PR	01/20/2016	OW	045-20305	SCHOOL HOUSE POINT OM02D B21 696	PR
421135	WELL	PR	01/19/2016	OW	045-20306	SCHOOL HOUSE POINT OM08D B21 696	PR
421136	WELL	PR	01/20/2016	OW	045-20307	SCHOOL HOUSE POINT OM02B B21 696	PR
421146	WELL	PR	09/12/2015	OW	045-20316	SCHOOL HOUSE POINT OM02C B21 696	PR

General Comment:**COGCC Inspection Report Summary**

On Tuesday 10/20/2020, I, Inspector Mike Longworth, conducted a inspection at BERRY PETROLEUM COMPANY LLC, SCHOOL HOUSE POINT OM B21 696, Location ID: 421108

During this inspection the following possible compliance issues were observed:

95 bbl tank with damaged label. 400 bbl tank not labeled.

Install sign to comply with Rule 210.d.

CA Date 01/22/2021

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	95 bbl tank with damaged label. 400 bbl tank not labeled.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	01/22/2021
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 11		
Comment:			

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 12		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 7		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Chemical containers		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)	Unlabeled	
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	<100 BBLS	PBV STEEL		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	95 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
----------	---	----------	------	---------	--------

CONDENSATE	5	400 BBLS	HEATED STEEL AST		,	
Comment:						
Corrective Action:						Date:
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment:						
Corrective Action:						Date:
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
Flaring:						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities									
Facility ID:	293396	Type:	WELL	API Number:	045-14956	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	293397	Type:	WELL	API Number:	045-14957	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421132	Type:	WELL	API Number:	045-20304	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421134	Type:	WELL	API Number:	045-20305	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421135	Type:	WELL	API Number:	045-20306	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421136	Type:	WELL	API Number:	045-20307	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421146	Type:	WELL	API Number:	045-20316	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Pass	
		Gravel	Pass			
Berms	Pass					
		Culverts	Pass			
Compaction	Pass					
Gravel	Pass					
		Ditches	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402515128	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5274239
701100615	Inspection 701100614 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5274236