

## Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S98W /25NWSE

Location ID: 312513



Photo #2151 from NW corner of location.



Photo #2152 from NW corner of location.

## Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S98W /25NWSE

Location ID: 312513



Photo #1836 from inspection #699801729 conducted on 9/2/20.



Photo #2153 Debris inside pit.

## Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S98W /25NWSE

Location ID: 312513



**Photo #1837 from inspection #699801729 conducted on 9/2/20.**



**Photo #2154 Debris around equipment.**