

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/06/2020

Submitted Date:

11/11/2020

Document Number:

688800821

FIELD INSPECTION FORM

Loc ID 326454 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10679
Name of Operator: LOGOS OPERATING LLC
Address: 2010 AFTON PLACE
City: FARMINGTON State: NM Zip: 87415

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 9 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Heil, John		john.heil@state.co.us	
Sessions, Tamra		tsessions@logosresourcesllc.com	All Inspections
Rowley, Darren		drowley@logosresourcesllc.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216524	WELL	PR	07/01/2020	GW	067-08130	IGNACIO 33-7 2A	EI

General Comment:

On November 6, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Logos Operating LLC Ignacio 33-7 #2A. For the most recent field inspection report of this facility, please refer to document #693902148.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Sign mounted to fencing around secondary containment berm. Contents, capacity and NFPA placard present on sign. Capacity on sign is listed as 55 bbl., open topped tank is 120 bbl. capacity.		
Corrective Action:	Install sign to comply with Rule 210.d.		Date: 01/11/2021
Type	WELLHEAD		
Comment:	Location sign mounted to meter run shack.		
Corrective Action:			Date:

Emergency Contact Number:

Comment:	Posted on location signs.		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	
In Containment: No _____			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	TANK BATTERY		
Comment:	Post and wire fencing around perimeter of secondary containment berm.		
Corrective Action:			Date:

Equipment:			corrective date
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			

Corrective Action:	Date:
--------------------	-------

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	Open Top		37.085560,-107.628115

Comment: Open topped steel PBV with expanded metal lid.

Corrective Action:	Date:
--------------------	-------

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	120 bbl.	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:

Corrective Action:	Date:
--------------------	-------

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 216524 Type: WELL API Number: 067-08130 Status: PR Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
On November 6, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Logos Operating LLC Ignacio 33-7 #2A. For the most recent field inspection report of this facility, please refer to document #693902148. During this inspection it was observed that the sign for the PBV indicates a capacity of 55 bbl. and the vessel is stamped with 120 bbl. capacity on the label.	hughesjo	11/11/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800822	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5289266