

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402408095

Date Received:

05/28/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

TEP

Phone

970-285-9377

Email

COGCCInspectionReports@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 700700789

Inspection Date: 05/27/2020

FIR Submit Date: 05/27/2020

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 311677

Location Name: HARRIS-67S94W Number: 5SWNE County: _____

Qtrqr: SWNE Sec: 5 Twp: 7S Range: 94W Meridian: 6

Latitude: 39.468371 Longitude: -107.910263

FACILITY - API Number: 05-045- -00 Facility ID: 311677

Facility Name: HARRIS-67S94W Number: 5SWNE

Qtrqr: SWNE Sec: 5 Twp: 7S Range: 94W Meridian: 6

Latitude: 39.468371 Longitude: -107.910263

CORRECTIVE ACTIONS:

1 ☒ CA# 139319

Corrective Action: Slope's need to be stabilized. Install or repair required BMPs.

Date: 07/08/2020

Response: CA COMPLETED

Date of Completion: 05/28/2020

Operator
Comment:

The cut slope is directly behind the separators and there is no way to stabilize the slope until final reclamation of the location. Additional disturbance of the slope will further destabilize the slope and could result in greater harm than benefit. This is not a storm water issue / violation, nor is this a safety issue. TEP monitors and inspects all locations continuously and performs maintenance as needed to maintain safe operations. No further actions are planned.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: The cut slope is directly behind the separators and there is no way to stabilize the slope until final reclaim of the location. Any additional disturbance of the slope will further destabilize the slope and could result in greater harm than benefit. This is not a storm water issue / violation, nor is this a safety issue. TEP monitors and inspects all locations continuously and performs maintenance as needed to maintain safe operations. No further actions are planned.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: _____

Title: TEP Environmental

Date: 5/28/2020 3:23:29 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402408095	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files