

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402532789

Date Received:  
11/19/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10720

Name of Operator: KODA EXPLORATION LLC

Address: 2443 SOUTH UNIVERSITY BLVD 215

City: DENVER State: CO Zip: 80210

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Joseph Rezendez</u>		<u>rezenjp@gmail.com</u>
<u>SULLIVAN RYAN</u>		<u>rsullivanvc@gmail.com</u>
<u>ELGERD ANDERS</u>		<u>elgerd@comcast.net</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 690200797

Inspection Date: 11/05/2020

FIR Submit Date: 11/09/2020

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: KODA EXPLORATION LLC

Company Number: 10720

Address: 2443 SOUTH UNIVERSITY BLVD 215

City: DENVER State: CO Zip: 80210

LOCATION - Location ID: 472992

Location Name: Roaring Fork Number: 14-28 Pad County: LINCOLN

Qtrqtr: SESW Sec: 28 Twp: 16S Range: 54W Meridian: 6

Latitude: 38.627090 Longitude: -103.460720

FACILITY - API Number: 05-073-00 Facility ID: 472941

Facility Name: Roaring Fork Number: 14-28

Qtrqtr: SESW Sec: 28 Twp: 16S Range: 54W Meridian: 6

Latitude: 38.627090 Longitude: -103.460720

CORRECTIVE ACTION:

1 CA# 144252

Corrective Action: Comply with 1002.c

Date: \_\_\_\_\_

Response: CA COMPLETED

Date of Completion: 11/19/2020

Operator Comment: Hydromulch with tackifier was applied to stockpiled topsoil to stabilize and as a best management practice to protect from degradation due to wind and water erosion in compliance with rule 1002.c (Photographs attached).

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Hydromulch with tackifier was applied to stockpiled topsoil to stabilize and as a best management practice to protect from degradation due to wind and water erosion in compliance with rule 1002.c (Photographs attached).

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Chris Del Hlerro

Signed: \_\_\_\_\_

Title: Agent

Date: 11/19/2020 4:39:42 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
402536730	View of topsoil stabilization from pad entrance facing west
402536734	View of topsoil stabilization from southeast corner of pad facing north
402536735	View of topsoil stabilization from pad entrance facing east
402536737	View of topsoil stabilization from northeast corner of pad facing west
402536739	View of topsoil stabilization from northwest corner of pad facing south

Total Attach: 5 Files