

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/01/2020

Submitted Date:

12/03/2020

Document Number:

696202065

**FIELD INSPECTION FORM**Loc ID 314281 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10027

Name of Operator: C &amp; J FIELD SERVICES

Address: 3650 COUNTY RD #2

City: RANGELY State: CO Zip: 81648

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name    | Phone | Email                        | Comment |
|-----------------|-------|------------------------------|---------|
| Murray, Richard |       | g.richard.murray@state.co.us |         |
|                 |       | candjfield@centurytel.net    |         |

**Inspected Facilities:**

| Facility ID | Type     | Status | Status Date | Well Class | API Num   | Facility Name                  | Insp Status |
|-------------|----------|--------|-------------|------------|-----------|--------------------------------|-------------|
| 228179      | WELL     | PA     | 08/17/2012  | OW         | 103-01123 | SMITH-HARRIS 2-2               | PA          |
| 314281      | LOCATION | CL     |             |            | -         | SMITH-HARRIS-61N102W<br>10NENW | RI          |

**General Comment:**

On 12/1/2020, Reclamation Specialist Trujillo conducted a final reclamation and stormwater inspection at C&J Field Service's Smith-Harris #2-2 location in Rio Blanco County, Colorado.

This inspection is a follow up to inspection #692400855 and #696201120 to document compliance for the following corrective actions:

1004: Comply with 1004 rules and conduct reclamation, remove surface equipment.

On 7/9/2020, Operator contacted Reclamation specialist regarding the corrective actions. Operator stated above ground flowline and electrical equipment remaining on the Location is still in use. Operator was directed to submit a Form 4 sundry identifying the equipment's current use on the location, and wells equipment is associated with. To date no documentation has been submitted by Operator.

It was observed in this inspection that flowline and electrical equipment remains on Location. It was also observed that the flowline equipment identified by the Operator does not appear to have been registered/mapped pursuant to the 1100 Rules. Additionally, flowline integrity concerns still exist as leaks and corrosion remain evident.

Refer to the "Reclamation" section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Inspected Facilities**

Facility ID: 228179 Type: WELL API Number: 103-01123 Status: PA Insp. Status: PA

**Flowline**

|    |       |            |
|----|-------|------------|
| #1 | Type: | 1 of Lines |
|----|-------|------------|

Flowline Description

Flowline Type: Size: Material:  
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:  
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

☒ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: Previous and current inspections observed flowline riser and pipe equipment remaining on the Location with integrity concerns (leaks/corrosion). Previous inspections required Operator to comply with 1004 rules and remove. Corrective actions have not been addressed; Integrity concerns also not addressed.

Corrective Action: There are three corrective actions being provided:

- 1) Immediately maintain active and inactive flowlines and crude oil transfer lines to meet 1102 Rules.
- 2) Immediately contact COGCC Western Integrity Inspector R. Murray (g.richard.murray@state.co.us) and provide annual pressure testing data per Rule 1104.f. (1)A attached to a Form 4 Sundry.
- 3) Immediately submit an eForm 44 Flowline Report for flowline registration pursuant to 1101 Rules: An off-location flowline in existence prior to May 1, 2018, required registration by October 31, 2019.

Note to Operator: Ensure all off-location flowlines meet the 1100 Series Rules.

Date: 10/31/2019

Facility ID: 314281 Type: LOCATION API Number: - Status: CL Insp. Status: RI

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads \_\_\_\_\_ Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed **Fail** \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment:

|   |  |                        |
|---|--|------------------------|
| Corrective Action:  | <p>It was observed in this inspection that flowline and electrical equipment remain on the Location. See "related facilities" for additional information regarding flowline. Corrective action requiring reclamation and removal of electrical equipment has not been addressed.</p> <p>Entire access road has not been reclaimed per the corrective actions. See Photo 6. No evidence of desirable perennial vegetative germination, reseeding is required.</p> <p>Inspection #692400855 required reclamation activities to be completed by end of Fall 2019; The CA date of 12/20/2019 remains applicable.</p> | Date <b>12/20/2019</b> |
|   | <p>Comply with Rule 1004.a: Perform Final Reclamation per COGCC 1004 Rules including removal of equipment/risers, stained soil, de-compaction &amp; re-seeding of site, and reclamation of access road. Install appropriate BMPs to stabilize location until vegetation establishes.</p>   |                        |
| Overall Final Reclamation <b>Fail</b> Well Release on Active Location <input type="checkbox"/> Multi-Well Location <input type="checkbox"/> |  |                        |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 402546271    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5302808">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5302808</a> |
| 696202066    | Inspection Photos    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5302783">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5302783</a> |