

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

03/04/2021

Submitted Date:

03/04/2021

Document Number:

699103228

FIELD INSPECTION FORM
 Loc ID 413974 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

13 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Evins, Bret		bret.evins@state.co.us	
,		EHSRC@bonanzacrk.com	All Inspections
Kraich, Adam		adam.kraich@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412522	WELL	TA	10/01/2019	OW	123-30518	NORTH PLATTE 41-34	TA
429081	WELL	TA	02/06/2020	OW	123-35676	North Platte 42-34	TA
432063	WELL	PR	11/01/2019	OW	123-36937	North Platte U-Y-34HNB	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:	Tote next to gaslift riser needs placards due to them being weathered "Sign not legible". See attached photo.		
Corrective Action:	Install sign to comply with Rule 605.h	Date:	03/16/2021
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	Adequate
Corrective Action:	
Date:	

Good Housekeeping:			
Type	OTHER		
Comment:	Stained soil at the North Platte U-Y-34 needs to be removed for good housekeeping. See attached photo.		
Corrective Action:	"Properly dispose of oily waste in accordance with 905.e."	Date:	03/16/2021
Type	UNUSED EQUIPMENT		
Comment:	Unused Equipment in multiple locations, needs to be removed for good housekeeping. See attached photo.		
Corrective Action:	Comply with Rule 606	Date:	03/16/2021

Overall Good: ☐

Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Other	#		
Comment:	Master valve on the North Platte U-Y-34 appears to be leaking. See attached photos.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date: 03/16/2021
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 3		
Comment:	Appear to be plumbed to surface.		

Corrective Action:		Date:	
<u>Venting:</u>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
<u>Flaring:</u>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 412522 Type: WELL API Number: 123-30518 Status: TA Insp. Status: TA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: T/A

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 04/13/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 429081 Type: WELL API Number: 123-35676 Status: TA Insp. Status: TA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: T/A

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 02/13/2020 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Well needs updated annual bradenhead test on file. Submit reports.

Corrective Action: _____ Date: _____

Facility ID: 432063 Type: WELL API Number: 123-36937 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 04/13/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday 3/4/21 at approximately 0741hrs, I, Inspector Adam Burns, Conducted an on-site inspection at North Platte P-T-34HZ Pad of Bonanza Creek Energy, at Location ID # 429920 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Tote next to gaslift riser needs placards due to them being weathered "Sign not legible".</p> <p>Install sign to comply with Rule 605.h. With a corrective action date of 3/16/21.</p> <p>Unused Equipment in multiple locations, needs to be removed for good housekeeping.</p> <p>Comply with Rule 606. With a corrective action date of 3/16/21.</p> <p>Stained soil at the North Platte U-Y-34 needs to be removed for good housekeeping.</p> <p>"Properly dispose of oily waste in accordance with 905.e." With a corrective action date of 3/16/21.</p> <p>Master valve on the North Platte U-Y-34 appears to be leaking. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.</p> <p>North Platte 42-34 well needs updated annual bradenhead test on file. Submit reports.</p> <p>See attached photos.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	burnsa	03/04/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699103229	Inspection Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5367716