

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/18/2021

Submitted Date:

03/23/2021

Document Number:

701101293

FIELD INSPECTION FORM

Loc ID 323873 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

- 12 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerusoilandgas.com	Piceance inspections only
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211054	WELL	SI	09/01/2020	GW	045-06812	TEXACO FEE 6218	PR

General Comment:

COGCC Inspection Report Summary of A follow up to 11/05/2020 Inspection # 701100720
Location is in close proximity of Roan Creek and in a High Priority Habitat Area. (Elk Migration Corridor, Elk Winter Concentration Area, Mule Deer Winter Concentration Area)
Trash (wood pallett) has been removed from location.
During this inspection the following un resolved compliance issues were observed:
Emergency phone # not legible on battery sign. Operator phone # and nearest road not on sign.
No NFPA sticker on Production water tank.
Access road and location shows signs of lack of stabilization BMP's in some areas. Storm water washing over edge of location at separator and tank battery. Culvert on access road just past gate needs maintained. Impoundment of storm water in earthen tank berm.
A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location			
Lease Road:			
Type	Main		
comment:	County road		
Corrective ActionL			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:	Battery sign not at tank battery.Operator phone # not legible on battery sign. Operator phone # and nearest road noton sign.		
Corrective Action:	Install sign to comply with Rule 605.e.		Date: 02/10/2021
Type	TANK LABELS/PLACARDS		
Comment:	No NFPA sticker on Production water tank.		
Corrective Action:	Install sign to comply with Rule 605.h.		Date: 02/10/2021
Type	WELLHEAD		
Comment:	No api # on well sign.		
Corrective Action:	Install sign to comply with Rule 605.d.		Date: 02/10/2021
Emergency Contact Number:			
Comment:	911 (Emergency number and nearest road post on tank not on battery sign)		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	TRASH		
Comment:	Wood pallett removed from location.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	SEPARATOR		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:			

Corrective Action:		Date:	
Equipment:			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Braden head accessible for monitoring.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 211054 Type: WELL API Number: 045-06812 Status: SI Insp. Status: PR

Producing Well

Comment: [Producing well](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
		Culverts	Fail			
Ditches						
				Material Handling And Spill Prevention	Fail	Impoundment of storm water in earthen tank berm.
Gravel						
Compaction						
		Gravel				

Comment: Access road and location shows signs of lack of stabilization BMP's in some areas. Storm water washing over edge of location at separator and tank battery. Culvert on access road just past gate needs maintained. Impoundment of storm water in earthen tank berm.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 11/24/2020

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701101304	Inspection 701101293 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5384041