

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/30/2021

Submitted Date:

03/31/2021

Document Number:

701500140

**FIELD INSPECTION FORM**Loc ID 315691 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10112

Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC

Address: 5057 KELLER SPRINGS RD STE 650

City: ADDISON State: TX Zip: 75001

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

9 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name       | Phone | Email                           | Comment    |
|--------------------|-------|---------------------------------|------------|
| Energy, Foundation |       | regulatory@foundationenergy.com | Regulatory |
| Thompson, Bud      |       | BLThomps@BLM.gov                |            |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name               | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------------|-------------|
| 231356      | WELL | SI     | 05/01/2020  | GW         | 103-09026 | RANGELY SOUTH FED 9-4-1-102 | SI          |

**General Comment:**

A follow up inspection of FIR document 700405207.

The following compliance issues were resolved:

- 1) Bradenhead acces was added.

The following compliance issues are uncompleted:

- 1) Well sign missing. Photo 4. Complete by 4-30-2021.

This is a summary of inspection report 701500140.

**Location**Overall Good: ☒

|                      |  |       |            |
|----------------------|--|-------|------------|
| <b>Signs/Marker:</b> |  |       |            |
| Type                 | TANK LABELS/PLACARDS                             |       |            |
| Comment:             |  |       |            |
| Corrective Action:   |  | Date: |            |
| Type                 | WELLHEAD   |       |            |
| Comment:             | Well sign is missing. Frame for sign is present. |       |            |
| Corrective Action:   | Install sign to comply with Rule 605.d.          | Date: | 04/30/2021 |
| Type                 | BATTERY  |       |            |
| Comment:             | Sign at meter building.                          |       |            |
| Corrective Action:   |  | Date: |            |

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                                   |                            |       |                 |
|-----------------------------------|----------------------------|-------|-----------------|
| <b>Equipment:</b>                 |                            |       | corrective date |
| Type: Bird Protectors             | # 1                        |       |                 |
| Comment:                          |                            |       |                 |
| Corrective Action:                |                            | Date: |                 |
| Type: Bradenhead                  | # 1                        |       |                 |
| Comment:                          | Bradenhead access present. |       |                 |
| Corrective Action:                |                            | Date: |                 |
| Type: Gas Meter Run               | # 1                        |       |                 |
| Comment:                          | Telemetry.                 |       |                 |
| Corrective Action:                |                            | Date: |                 |
| Type: Deadman # & Marked          | # 4                        |       |                 |
| Comment:                          |                            |       |                 |
| Corrective Action:                |                            | Date: |                 |
| Type: Horizontal Heated Separator | # 1                        |       |                 |
| Comment:                          |                            |       |                 |
| Corrective Action:                |                            | Date: |                 |

**Tanks and Berms:**

|          |   |          |      |         |        |
|----------|---|----------|------|---------|--------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
|----------|---|----------|------|---------|--------|

|                    |          |                     |                     |             |   |       |
|--------------------|----------|---------------------|---------------------|-------------|---|-------|
| PRODUCED WATER     | 1        | <50 BBLS            | FIBERGLASS AST      |             | , |       |
| Comment:           |          |                     |                     |             |   |       |
| Corrective Action: |          |                     |                     |             |   | Date: |
| <b>Paint</b>       |          |                     |                     |             |   |       |
| Condition          | Adequate |                     |                     |             |   |       |
| Other (Content)    |          |                     |                     |             |   |       |
| Other (Capacity)   | 40 bbl   |                     |                     |             |   |       |
| Other (Type)       |          |                     |                     |             |   |       |
| <b>Berms</b>       |          |                     |                     |             |   |       |
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |   |       |
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |   |       |
| Comment:           |          |                     |                     |             |   |       |
| Corrective Action: |          |                     |                     |             |   | Date: |
| <b>Venting:</b>    |          |                     |                     |             |   |       |
| Yes/No             | NO       |                     |                     |             |   |       |
| Comment:           |          |                     |                     |             |   |       |
| Corrective Action: |          |                     |                     |             |   | Date: |
| <b>Flaring:</b>    |          |                     |                     |             |   |       |
| Type               |          |                     |                     |             |   |       |
| Comment:           |          |                     |                     |             |   |       |
| Corrective Action: |          |                     |                     |             |   | Date: |

**Inspected Facilities**Facility ID: 231356 Type: WELL API Number: 103-09026 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Last recorded production April 2020.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms            |                 |                         |                       |               |                          |         |

Comment: No significant soil migration; erosion or soil movement on location.

Corrective Action:

Date:

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 402644896    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5391075">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5391075</a> |
| 701500141    | inspection photos    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5391071">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5391071</a> |