

Inspection Photos
Location Name: UPRR 43 PAN AM I#25
Location ID: 318383



Photo 1 WH Debris: dead weeds on location and in ditch.



Photo 2 Unused equipment : Cement base, electric control box.

Inspection Photos
Location Name: UPRR 43 PAN AM I#25
Location ID: 318383



Colorado Oil and Gas Conservation Commission
40.05365, -104.9588, 1546.0m
Apr 13, 2021 11:27:34

Photo 3 Site Remediation: Pipeline open excavation has been open since 4-4-18.



Colorado Oil and Gas Conservation Commission
40.05363, -104.95879, 1545.4m
Apr 13, 2021 11:27:45

Photo 4 open excavation.

Inspection Photos
Location Name: UPRR 43 PAN AM I#25
Location ID: 318383



Photo 5 Unused equipment: electric panel, Meter has been removed.



Photo 6 open excavation no BMP's.

Inspection Photos
Location Name: UPRR 43 PAN AM I#25
Location ID: 318383



Photo 7 open excavation facing North. No fencing and or BMP's.



Photo 8 Debris: Dead weeds on location. Unused equipment Cement base and electric control box.

Inspection Photos
Location Name: UPRR 43 PAN AM I#25
Location ID: 318383



Photo 9 Well Head House facing North residents Home is approx..250 ft from WH. Debris: dead weeds on location.



Photo 10 Well head facing North West Residents homes are approx. 195 ft from WH