

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|--|-------|------------|
| Type | TANK LABELS/PLACARDS | | |
| Comment: | The capacity label for the pit is faded. See attached photo. | | |
| Corrective Action: | Install sign to comply with Rule 605.g. | Date: | 06/04/2021 |

Emergency Contact Number:

| | | | |
|--------------------|----------|-------|--|
| Comment: | Adequate | Date: | |
| Corrective Action: | | Date: | |

Good Housekeeping:

| | | | |
|--------------------|---|-------|------------|
| Type | UNUSED EQUIPMENT | | |
| Comment: | Unused equipment in multi locations needs to be removed for good housekeeping. See attached photos. | | |
| Corrective Action: | Comply with Rule 606 | Date: | 06/04/2021 |

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|----------|-------|--|
| Type | WELLHEAD | | |
| Comment: | Panel | | |
| Corrective Action: | | Date: | |

Equipment:

| Type | # | Comment | Corrective Action | Date | corrective date |
|-----------------|-----|--|--|------------|-----------------|
| Bird Protectors | # 1 | | | | |
| Bradenhead | # 1 | Appears to be plumbed to surface. | | | |
| Gas Meter Run | # 1 | Meter not calibrated annually. See attached photo. | Calibrate gas metering equipment annually to comply with rule 430.d.(1). | 06/04/2021 | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|----------------|----------------------|----------|--------------|---------|--------|
| PRODUCED WATER | 1 | OTHER | PBV CONCRETE | | , |
| Comment: | <input type="text"/> | | | | |

| | |
|--------------------|-------|
| Corrective Action: | Date: |
|--------------------|-------|

Paint

| | | | |
|------------------|--------|--|--|
| Condition | | | |
| Other (Content) | | | |
| Other (Capacity) | 48 BBL | | |
| Other (Type) | | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|-----------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL | 1 | 300 BBLs | STEEL AST | | 40.348200,-104.596900 |

| | | | | |
|--------------------|--|--|--|-------|
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Paint

| | | | |
|------------------|----------|--|--|
| Condition | Adequate | | |
| Other (Content) | | | |
| Other (Capacity) | | | |
| Other (Type) | | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | | |
|--------------------|--|--|-------|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Inspected Facilities

Facility ID: 270169 Type: WELL API Number: 123-21834 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

BradenHead

Date of Last Brhd Test: 03/01/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 130 Fluid Type: NONE

End Surf Csg Pressure: 1

Comment:

Corrective Action: Date: _____

COGCC Comments

| Comment | User | Date |
|--|--------|------------|
| <p>COGCC Inspection Report Summary On Tuesday 4/27/21 at approximately 1030hrs, I, Inspector Adam Burns, Conducted an on-site inspection at ARD C 06-29D of Noble Energy, at Location ID # 332100 in Weld County, Colorado. During this inspection the following possible compliance issues were observed: Unused Equipment needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 6/4/21. Stained Soil under master valve at the well needs to be removed. "Properly dispose of oily waste in accordance with 905.e." With a corrective action date of 6/4/21. The capacity label for the pit is faded. Install sign to comply with Rule 605.g. With a corrective action date of 6/4/21. Meter not calibrated annually. Calibrate gas metering equipment annually to comply with rule 430.d.(1). With a corrective action date of 6/4/21. See attached photos. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p> | burnsa | 04/27/2021 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 699103455 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5414657 |