

Inspection Photos  
Operator: Simcoe  
API: 067-07463  
Date: 4/22/2021



Photo 1. View of the project area from the northeastern corner facing center.





Photo 2. View of the eastern project area from the northwestern corner facing eastward. Revegetation is progressing with western wheatgrass, crested wheatgrass, and rubber rabbitbrush.





Photo 3. View of the northern project area from the northeastern corner facing westward.



Debris



Musk thistle  
rosettes



Photos 4/5. View of appliance dumped off of the northern edge of the well pad (left), and musk thistles observed within the interim reclamation area (right).





Photo 6. View of the reference area comprised of pinyon and juniper woodland with sagebrush shrubland, blue grama, Indian ricegrass, and mat penstemon.