

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

04/21/2021

Submitted Date:

04/23/2021

Document Number:

700702619

FIELD INSPECTION FORM
 Loc ID 432336 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

21 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
432332	WELL	PR	05/17/2014	GW	045-21962	Savage RWF 21-25	PR
432333	WELL	PR	05/19/2014	GW	045-21963	Savage RWF 521-25	PR
432334	WELL	PR	03/01/2014	GW	045-21964	Savage RWF 422-25	PR
432335	WELL	PR	03/01/2014	GW	045-21965	Savage RWF 522-25	PR
432337	WELL	PR	04/12/2014	GW	045-21966	Savage RWF 322-25	PR
432338	WELL	PR	04/12/2014	GW	045-21967	Savage RWF 11-25	PR
432339	WELL	PR	05/19/2014	GW	045-21968	Savage RWF 421-25	PR
432340	WELL	PR	04/12/2014	GW	045-21969	Savage RWF 511-25	PR
432341	WELL	PR	05/18/2014	GW	045-21970	Savage RWF 321-25	PR
432342	WELL	PR	12/12/2013	GW	045-21971	Savage RWF 512-25	PR
432343	WELL	PR	04/08/2014	GW	045-21972	Savage RWF 411-25	PR
432344	WELL	PR	03/01/2014	GW	045-21973	Savage RWF 22-25	PR
432345	WELL	PR	03/11/2014	GW	045-21974	Savage RWF 12-25	PR
432346	WELL	PR	02/12/2014	GW	045-21975	Savage RWF 312-25	PR
432347	WELL	PR	03/01/2014	GW	045-21976	Savage RWF 412-25	PR
432348	WELL	PR	04/08/2014	OW	045-21977	Savage RWF 311-25	PR

General Comment:

COGCC Inspection Report Summary

On Wednesday 4/21/2021 at approximately 1100, I, Inspector Scott Ramsey, conducted a routine inspection at TEP RWF 22-25, at Location # 432336 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Also location is within or in close proximity to the 411 water protection area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for tracking pad.

During this inspection the following compliance issues were observed:

1. Location and cut slope behind tank battery shows signs of lack of stabilization/compaction.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Bradenhead	# 16		corrective date
Comment:	Braden heads have telemetry for monitoring.		
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	

Type: Deadman # & Marked	# 8	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 4	
Comment:	chemical tanks at well heads in plastic containments	
Corrective Action:		Date:
Type: Bird Protectors	# 9	
Comment:		
Corrective Action:		Date:
Type: Emission Control Device	# 1	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 16	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 16	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type	Ignitor/Combustor	
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	432332	Type:	WELL	API Number:	045-21962	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	432333	Type:	WELL	API Number:	045-21963	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	432334	Type:	WELL	API Number:	045-21964	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	432335	Type:	WELL	API Number:	045-21965	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	432337	Type:	WELL	API Number:	045-21966	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	432338	Type:	WELL	API Number:	045-21967	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	432339	Type:	WELL	API Number:	045-21968	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	432340	Type:	WELL	API Number:	045-21969	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			

Facility ID:	432341	Type:	WELL	API Number:	045-21970	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	432342	Type:	WELL	API Number:	045-21971	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	432343	Type:	WELL	API Number:	045-21972	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	432344	Type:	WELL	API Number:	045-21973	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	432345	Type:	WELL	API Number:	045-21974	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	432346	Type:	WELL	API Number:	045-21975	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	432347	Type:	WELL	API Number:	045-21976	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	432348	Type:	WELL	API Number:	045-21977	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
Compaction	Fail					
Ditches						
		Ditches				
		Culverts				

Comment: This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Also location is within or in close proximity to the 411 water protection area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for tracking pad.
1. Location and cut slope behind tank battery shows signs of lack of stabilization/compaction.

Corrective Action: **Install or repair required BMPs**

Date: 05/31/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402669777	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5411986
700702627	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5411975