

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

04/27/2021

Submitted Date:

04/27/2021

Document Number:

699103454**FIELD INSPECTION FORM**
 Loc ID 332100 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|----------------------------------------|---------------------------------|
| , | | NBL_DJBU_Inspections@NB LENERGY.COM | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 270169 | WELL | TA | 07/01/2019 | GW | 123-21834 | ARD C 6-3JI | TA |

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

| | | | |
|--------------------|--------------------------------------------------------------|-------|------------|
| Type | TANK LABELS/PLACARDS | | |
| Comment: | The capacity label for the pit is faded. See attached photo. | | |
| Corrective Action: | Install sign to comply with Rule 605.g. | Date: | 06/04/2021 |

Emergency Contact Number:

| | | | |
|--------------------|----------|-------|--|
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |

Good Housekeeping:

| | | | |
|--------------------|-----------------------------------------------------------------------------------------------------|-------|------------|
| Type | UNUSED EQUIPMENT | | |
| Comment: | Unused equipment in multi locations needs to be removed for good housekeeping. See attached photos. | | |
| Corrective Action: | Comply with Rule 606 | Date: | 06/04/2021 |

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|----------|-------|--|
| Type | WELLHEAD | | |
| Comment: | Panel | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|-----------------------|--------------------------------------------------------------------------|-------|-----------------|
| Type: Bird Protectors | # 1 | | corrective date |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | Appears to be plumbed to surface. | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | Meter not calibrated annually. See attached photo. | | |
| Corrective Action: | Calibrate gas metering equipment annually to comply with rule 430.d.(1). | Date: | 06/04/2021 |

Tanks and Berms:

| | | | | | | |
|----------------|---|----------|--------------|---------|--------|--|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| PRODUCED WATER | 1 | OTHER | PBV CONCRETE | | , | |
| Comment: | | | | | | |

| | | | |
|--------------------|--|-------|--|
| Corrective Action: | | Date: | |
|--------------------|--|-------|--|

Paint

| | | |
|------------------|--------|--|
| Condition | | |
| Other (Content) | | |
| Other (Capacity) | 48 BBL | |
| Other (Type) | | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| | | | | | |
|--------------------|---|----------|-----------|---------|-----------------------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CRUDE OIL | 1 | 300 BBLs | STEEL AST | | 40.348200,-104.596900 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected FacilitiesFacility ID: 270169 Type: WELL API Number: 123-21834 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: T/A

Corrective Action: _____ Date: _____

BradenHeadDate of Last Brhd Test: 03/01/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 130 Fluid Type: NONEEnd Surf Csg Pressure: 1

Comment: _____

Corrective Action: _____ Date: _____

COGCC Comments

| Comment | User | Date |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|------------|
| <p>COGCC Inspection Report Summary</p> <p>On Tuesday 4/27/21 at approximately 1030hrs, I, Inspector Adam Burns, Conducted an on-site inspection at ARD C 06-29D of Noble Energy, at Location ID # 332100 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Unused Equipment needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 6/4/21.</p> <p>Stained Soil under master valve at the well needs to be removed. "Properly dispose of oily waste in accordance with 905.e." With a corrective action date of 6/4/21.</p> <p>The capacity label for the pit is faded. Install sign to comply with Rule 605.g. With a corrective action date of 6/4/21.</p> <p>Meter not calibrated annually. Calibrate gas metering equipment annually to comply with rule 430.d.(1). With a corrective action date of 6/4/21.</p> <p>See attached photos.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> | burnsa | 04/27/2021 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 402672959 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5414669 |
| 699103455 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5414657 |