

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/18/2021

Submitted Date:

05/18/2021

Document Number:

700702751

FIELD INSPECTION FORM
 Loc ID 335445 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10531

Name of Operator: GRIZZLY OPERATING LLC

Address: 5847 SAN FELIPE #3000

City: HOUSTON State: TX Zip: 77057

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278949	WELL	PR	04/07/2006	GW	045-10965	HERRERA 33D-20-692	PR
278950	WELL	PR	04/09/2006	GW	045-10964	HERRERA 43B-20-692	PR
278951	WELL	PR	03/31/2006	GW	045-10963	HERRERA 33B-20-692	PR
278952	WELL	PR	04/08/2006	GW	045-10962	HERRERA 43D-20-692	PR

General Comment:**COGCC Inspection Report Summary**

On Monday 5/17/2021 at approximately 1000, I, Inspector Scott Ramsey, conducted a follow up inspection at TEP Herrera, at Location # 335445 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad, there is no evidence of a tracking pad at time of inspection. C/A's from previous inspection document # 700701998 have NOT been completed.

During this inspection the following compliance issues were observed:

1. Location shows signs of lack of stabilization C/A is from previous inspection Document # 700701998 (C/A date 1/11/2021)

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Type	SEPARATOR			
Comment:				
Corrective Action:			Date:	

Equipment:			corrective date
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	chemical tank at well heads		
Corrective Action:			Date:
Type: Bradenhead	# 4		
Comment:	Braden heads have a port for manual gauge monitoring		
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 7		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	5	200 BBLS	HEATED STEEL AST		,	
Comment:	One (1) tank is NOT heated					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
	Date:			

Venting:

Yes/No	NO	
--------	----	--

Comment:			
Corrective Action:		Date:	
Flaring:			
Type	Ignitor/Combustor		
Comment:			
Corrective Action:		Date:	

Inspected Facilities				
Facility ID: 278949	Type: WELL	API Number: 045-10965	Status: PR	Insp. Status: PR
Producing Well				
Comment:	producing			
Corrective Action:			Date:	
Facility ID: 278950	Type: WELL	API Number: 045-10964	Status: PR	Insp. Status: PR
Producing Well				
Comment:	producing			
Corrective Action:			Date:	
Facility ID: 278951	Type: WELL	API Number: 045-10963	Status: PR	Insp. Status: PR
Producing Well				
Comment:	producing			
Corrective Action:			Date:	
Facility ID: 278952	Type: WELL	API Number: 045-10962	Status: PR	Insp. Status: PR
Producing Well				
Comment:	producing			
Corrective Action:			Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Berms						
Compaction	Fail					
		Culverts				

Comment: This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad, there is no evidence of a tracking pad at time of inspection.
 1. Location shows signs of lack of stabilization C/A is from previous inspection Document # 700701998 (C/A date 1/11/2021)

Corrective Action: **Install or repair required BMPs**

Date: 01/11/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700702755	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5432862