

Inspection Photos

7/12/2021

Operator: NONSUCH NATURAL GAS INC #
10163

Location ID: 453726
Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 453726



Photo 1: Photo taken from the east end of the Location, facing south. Photos 1-3 provide an overview of the Location from south, west to north.

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 453726



July 12, 2021
39.5139312N 108.19575974W

Photo 2: See comments under photo 1.



Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 453726



July 12, 2021
39.51392814N 108.19576005W

Photo 3: See comments under photo 1.



Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 453726



July 12, 2021
39.5140516N 108.19587165W

Photo 4: Photo facing west. Photo shows metershed, separator equipment and methanol tank. Photo also shows bird protector equipment appears to be missing from top of the separator.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 453726



Photo 5: Photo taken from the west end of the Location, facing southwest. Photo shows example of noxious weeds (Musk thistle) observed on the location and access road.



Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 453726



Photo 6: Photo taken from the west end of the Location, facing southeast. Photo shows example of noxious weeds (Musk thistle) observed on the location and access road.



Inspection Photos
Operator Name: NONSUCH NATURAL GAS INC # 10163
Location ID: 453726



July 12, 2021
39.51410102N 108.19612707W

Photo 7: Photo taken from the west end of the Location, facing northeast. Photo shows various pipe equipment remain improperly stored behind the methanol tank. Photo also shows that wildlife protection equipment, such as netting, to prevent wildlife access to the tanks secondary containment BMP is missing.

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 453726



July 12, 2021
39.5137535N 108.19588303W

Photo 8: Photo taken from the Location entrance (south end of the Location), facing north. Photo shows erosion degradation due to stormwater runoff from the pad; stormwater runoff has resulted in erosion degradation and offsite sediment discharge at Location entrance and access road.



Inspection Photos
Operator Name: NONSUCH NATURAL GAS INC # 10163
Location ID: 453726



Photo 10: Photo taken from the Location entrance (south end of the Location), facing north. Photo shows erosion degradation due to stormwater runoff from the pad

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 453726



Photo 11: Photo taken from the Location entrance (south end of the Location), facing southeast. Photo shows stormwater runoff from the Location has resulting in erosion degradation on the access road, and off-site sediment transport.

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 453726



Photo 12: Photo taken from the access road, south of the Location. Photo shows stormwater erosion degradation on access road due to runoff from the Location.



Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 453726



Photo 13: Stormwater erosion on access road.

Inspection Photos
Operator Name: NONSUCH NATURAL GAS INC # 10163
Location ID: 453726



July 12, 2021
39.51295162N 108.19580759W

Photo 14: Photo taken from the access road. Photo shows sediment deposition resulting from stormwater runoff from the Location and erosion degradation.