

Inspection Photos
Operator: Simcoe
API: 067-06969
Date: 7/29/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the northern project area from the northwestern corner facing eastward. Revegetation is progressing within the project area with crested wheatgrass, western wheatgrass, and rubber rabbitbrush.




Photo 3. View of the eastern project area from the northeastern corner facing southward. Approximately 100 musk thistles observed along the eastern edge of the project area.



Photo 4. View of cable debris observed within the northern project area.



Photo 5. View of the reference area comprised of big sagebrush mosaic with narrow leaf cottonwoods, western wheatgrass, and gambel oaks.