

Inspection Photos

API: 025-06021

Operator: VAL ENERGY INC

Inspection Date: 8/23/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 025-06021 | Date: 8/23/2021

Inspection Photos



Photo 1. Facing west toward the location. The perennial vegetation has not re-established to a 80% of reference area levels.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 025-06021 | Date: 8/23/2021

Inspection Photos



Photo 2. Facing west at the north side of the location. This area is approximately 300' x 200' of mostly bare soil. The location needs to be reclaimed to re-establish perennial vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 025-06021 | Date: 8/23/2021

Inspection Photos



Photo 3. Facing east at the west side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 025-06021 | Date: 8/23/2021

Inspection Photos



Photo 4. Facing north at the south side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 025-06021 | Date: 8/23/2021

Inspection Photos



Photo 5. Facing west toward the surrounding undisturbed pasture which consists of a uniform native vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 025-06021 | Date: 8/23/2021