

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/09/2021

Submitted Date:

09/09/2021

Document Number:

689806344

FIELD INSPECTION FORM

 Loc ID 416625 Inspector Name: Waldron, Emily On-Site Inspection 2A Doc Num:
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 OGCC Operator Number: 10598
 Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLC
 Address: 123 ROBERT S KERR AVE
 City: OKLAHOMA CITY State: OK Zip: 73102
Findings:

- 6 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------------|--------------|--|---------------------------------|
| Inspections, General | | sandridgeenvironmental@sandridgeenergy.com | All Inspections |
| Kellerby, Shaun | | shaun.kellerby@state.co.us | |
| Boyer, David | 303-994-0000 | david@d90energy.com | |

General Comment:

Routine follow up inspection. Follow up to inspection from 5/18/2021 document number 689805811. No corrective actions appear to have been made. Form 9 to transfer from Sandridge to D90 received 5/12/2021 document number 402676753, form remains In Process.
 Compliance issues observed:
 entrance sign, wellhead sign, tank battery sign incomplete/inaccurate

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|---|-------|------------|
| Type | OTHER | | |
| Comment: | Entrance sign still contains former operator name. | | |
| Corrective Action: | Install sign to comply with Rule 605.a. | Date: | 10/09/2021 |
| Type | WELLHEAD | | |
| Comment: | Sign not posted or information inaccurate at well(s). Well signs must contain: the well name, the API number, and the legal location including the quarter/quarter section. | | |
| Corrective Action: | Install sign to comply with Rule 605.d. | Date: | 05/11/2021 |
| Type | BATTERY | | |
| Comment: | Tank battery sign incomplete. Tank Battery sign must include: operator name, telephone number where operator can be reached at all times, telephone number for local emergency services (911 where available), the public road used to access the site, well name, API numbers, and legal location for all wells associated with battery, location of battery including the quarter/quarter section. | | |
| Corrective Action: | Install sign to comply with Rule 605.e. | Date: | 05/11/2021 |

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 689806345 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5527753 |