

Inspection Photos
Operator: Petrox
API: 007-06099
Date: 9/13/2021



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing with western wheatgrass, gambel oak, Woods rose, and mugwort.




Photo 3. View of musk thistles within the southern project area. Approx. 100 individuals observed.



Photo 4. View of the reference area comprised of ponderosa pine forest with understory of gambel oak, Sandberg bluegrass, and serviceberry.