

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402815674

Date Received:

09/19/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

timothy.thomsen@state.co.us

Gee, Greg

903-987-0353

ggee@ogrisop.com

Fitzgerald, Edie

719-859-1394

efitzgerald@ogrisop.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 690201355

Inspection Date: 04/01/2021

FIR Submit Date: 04/02/2021

FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC

Company Number: 10672

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 308603

Location Name: APACHE CANYON-634S67W Number: 6SESW County: LAS ANIMAS

Qtrqtr: SESW Sec: 6 Twp: 34S Range: 67W Meridian: 6

Latitude: 37.107310 Longitude: -104.932030

FACILITY - API Number: 05-071- -00 Facility ID: 276190

Facility Name: APACHE CANYON Number: 6-14

Qtrqtr: SESW Sec: 6 Twp: 34S Range: 67W Meridian: 6

Latitude: 37.107310 Longitude: -104.932030

CORRECTIVE ACTIONS:

1 ☒ CA# 147995

Corrective Action: Conduct maintenance on equipment, cleanup stained material, and review self inspection processes.

Date: 04/09/2021

Response: CA COMPLETED

Date of Completion: 09/10/2021

MAINTENANCE HAS BEEN PERFORMED, THE IMPACTED SOIL NEAR THE LIQUID RING COMPRESSOR WAS REMOVED AND THE SELF INSPECTION PROCESS HAS BEEN REVIEWED.

Operator
Comment:

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 147996

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 05/07/2021

Response: CA COMPLETED

Date of Completion: 04/14/2021

Operator
Comment:

THE ROAD SURFACE WAS CROWNED TO CREATE SHEET FLOW AND ELIMINATE THE TIRE RUTS. RUN OFF FROM THE PAD/ACCESS ROAD WAS RE-DIRECTED TO AN ARMORED CALL OUT, DIVERTING WATER TOWARD A CULVERT INLET ALONG THE MAIN LEASE ROAD. ADDITIONAL GRAVEL WAS ADDED TO THE ROADWAY SURFACE FOR STABILIZATION.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: ALL CORRECTIVE ACTIONS HAVE BEEN ADDRESSED.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: _____

Title: Sr. Environmental Tech.

Date: 9/19/2021 2:54:58 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402815674	FIR RESOLUTION SUBMITTED
402815675	PHOTO LOG

Total Attach: 2 Files