

Inspection Photos

API: 071-06508

API: 071-06734

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 10/8/2021



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06508 | Date: 10/8/2021

Inspection Photos



Photo 1. There is a steel building along the access road where landowner has observed oil and gas vehicle parking off the designated road way blocking this building. All oil and gas vehicles must stay within access road boundary.
Lat/Long:37.23550,-104.69878



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06508 | Date: 10/8/2021

Inspection Photos



Photo 2. Further along the road toward the location are areas of erosion that need to be repaired. Stormwater is flowing past the culvert shown at red arrow.
Lat/Long:37.23760,-104.69906.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06508 | Date: 10/8/2021

Inspection Photos



Photo 3. Further along the road is erosion channeling along the center of the road. Areas of erosion and vehicle rutting need to be repaired and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06508 | Date: 10/8/2021

Inspection Photos



Photo 4. This area of stormwater diversion has filled in with sediment causing erosion to occur down the road side shown at red arrow. The stormwater diversion needs to be repaired with proper BMP installation such as a sediment trap.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06508 | Date: 10/8/2021

Inspection Photos



Photo 5. Similarly to previous photo, stormwater is not properly diverted at red arrow. This area of the road is not stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06508 | Date: 10/8/2021

Inspection Photos



Photo 6. There is a cattleguard that is filled in with sediment at Lat/Long: 37.24379,-104.68923.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06508 | Date: 10/8/2021

Inspection Photos



Photo 7. Facing northwest toward the location.



Inspection Photos



Photo 8. Facing west at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06508 | Date: 10/8/2021

Inspection Photos



Photo 9. Facing toward the pit. The portion of the pit shown at red arrow appears to be drilling mud in the pit that needs to be cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06508 | Date: 10/8/2021