

Inspection Photos  
Operator: Simcoe  
API: 067-09506  
Date: 10/27/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is progressing with a mixture of wheatgrasses.



Photo 3. View of the northern project area from the northwestern corner facing eastward.



Photo 4. View of dense kochia debris within the western project area, needs to be removed.



Photo 5. View of the reference area comprised of irrigated grass field with grasses such as meadow brome, orchard grass, perennial rygrass, and tall fescue.