

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/25/2021

Submitted Date:

10/28/2021

Document Number:

696203318

FIELD INSPECTION FORMLoc ID 439173 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
439173	LOCATION	AC			-	Youberg RU 44-7	RI

General Comment:

On 10/25/2021, Reclamation Specialist Trujillo conducted a stormwater inspection at TEP Rocky Mountain's Youberg RU 44-7 location in Garfield County, Colorado.

This inspection is a followup to #696203193 to document compliance for the following corrective actions:
1002.f: Stormwater

It was observed in this inspection that the Location remains out of compliance with COGCC rules and corrective actions.

Refer to inspection #696203193 for corrective actions regarding weed management

Refer to the "Stormwater" section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐**Signs/Marker:**

Type OTHER

Comment: Inspection #696203193 observed sign not posted at Location entrance.

It was observed in this inspection that signage has been installed at the Location entrance.

This CA has been addressed.

Corrective Action:

Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Inspection #696203193 observed that control measures on the Location were missing or insufficient:
 -Sediment traps on Location not constructed or maintained in proper functioning condition.
 -Control measures to stabilize/protect cut slopes of the Location missing or insufficient.

Inspection required Operator to comply with Rule 1002.f by 10/19/2021.

It was observed in this inspection that the sediment traps have not been installed or maintained in accordance with good engineering practices; control measures to stabilize/protect the cut slopes remain missing or insufficient.

CA has not been addressed and remains applicable.

Corrective Action: **Comply with Rule 1002.f**

Date: 10/19/2021

Pits: ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402855874	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5566484
696203319	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5566466