

Inspection Photos

Location Name: Thompson-Price 2

Location ID: 320156



Pic 1 wellhead, weeds unmanaged.



Pic 2 unused equipment by pump jack weeds unmanaged

Inspection Photos

Location Name: Thompson-Price 2

Location ID: 320156

Nov 10, 2021 at 2:30:26 PM
39.811566,-104.207167
Exmoor Rd
Byers CO 80103
United States
COGCC



Pic 3 separator house weeds unmanaged

Nov 10, 2021 at 2:28:16 PM
39.809982,-104.200588
Byers CO 80103
United States
COGCC



Pic 4 pumpjack motor, weeds unmanaged.

Inspection Photos

Location Name: Thompson-Price 2


Location ID: 320156

Nov 10, 2021 at 2:30:55 PM
39.811567,-104.207417
Exmoor Rd
ayers CO 80103
United States
COGCC



Pic 5 tanks, unable to inspect berms due to weed growth

Nov 10, 2021 at 2:30:37 PM
39.811566,-104.207167
Exmoor Rd
ayers CO 80103
United States
COGCC



Pic 6 separator/ECD weeds unmanaged on location.

Inspection Photos
Location Name: Thompson-Price 2
Location ID: 320156



Pic 7 Tanks,



Pic 8 tanks