

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/11/2021

Submitted Date:

11/11/2021

Document Number:

699503341

**FIELD INSPECTION FORM**Loc ID 320156 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 19035

Name of Operator: OVERLAND RESOURCES LLC

Address: SUITE C18 PMB 440

City: GREENWOOD State: CO Zip: 80121

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

12 Number of Comments

3 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Anderson, Robert	(303) 800-6175	admin@overlandresourcesllc.com	<a href="#">All Inspections</a>
Behrens, Vic	303-810-6382	behrens@netecin.net	<a href="#">Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202852	WELL	SI	07/01/2017	OW	001-08257	THOMPSON-PRICE 2	SI

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Inadequate berms around tank(s), and separator		
Corrective Action:	: Repair or install berms or other secondary containment devices per Rule 605.a.(4). Inadequate berms around tank(s) Corrective action Date 6/15/2020,	Date:	06/15/2020
Type	WEEDS		
Comment:	Weeds unmanaged on location, Stained soil around pump jack motor and gear box, Stained soil around produced water tanks, stained soil under loaout line to produced water tank.		
Corrective Action:	Comply with COGCC housekeeping rules.	Date:	06/15/2020

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Gas motor		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	marked with steel fence post		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		

Comment:	Unable to inspect due to weed growth on location	Date:	
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	Open Top		,
Comment:	netting appears to be adequate at time of inspection				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:	shares containment with oil tank			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:	Needs to be repaired.			
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:	Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:	Date:	

**Inspected Facilities**

Facility ID: 202852 Type: WELL API Number: 001-08257 Status: SI Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: According to COGCC data this well has been shut in since 7/1/17. Missing production data from 8/1/19 to present. This well has been shut in for more than 2 years and is in need of a MIT according to MIT rules. Contact COGCC engineering.

Corrective Action: Comply with COGCC MIT rules for wells that have been shut in more than 2 years.

Date: 11/11/2021

**BradenHead**

Date of Last Brhd Test: 12/31/2019 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: TSTM

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On 11/10/21 at approximately 1500 I, Inspector Justin Medina conducted an on-site inspection at:</p> <p>Well Name- Thompson-Price 2</p> <p>Company Name- Overland Resources LLC</p> <p>API- 05-001-08257</p> <p>In Adams County Colorado.</p> <p>While there, I observed SI well.</p> <p>This is a follow up inspection from document # 700900083 Corrective Actions are Delinquent</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Weeds unmanaged on location, Stained soil around pump jack motor and gear box, Stained soil around produced water tanks, stained soil under loaout line to produced water tank.</p> <p>Comply with COGCC housekeeping rules.6/15/20</p> <p>Inadequate berms around tank(s), and separator</p> <p>Repair or install berms or other secondary containment devices per Rule 605.a.(4).</p> <p>Inadequate berms around tank(s) Corrective action Date 6/15/2020,</p> <p>According to COGCC data this well has been shut in since 7/1/17. Missing production data from 8/1/19 to present. This well has been shut in for more than 2 years and is in need of a MIT according to MIT rules. Contact COGCC engineering.</p> <p>Comply with COGCC MIT rules for wells that have been shut in more than 2 years. 11/11/21</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	medinaj	11/11/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699503342	Inspection Pictures	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5579157">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5579157</a>