

Inspection Photos
Location Name: Argenta 33-10 #4-3
API: 05-067-08322



Argenta 33-10 #4-3 production equipment.



Regulator on prime mover supply gas was broken and had an audible leak.

Inspection Photos
Location Name: Argenta 33-10 #4-3
API: 05-067-08322



Well head and surrounding area are wet and stained.



AST signage is not compliant with Rule 605.h.