

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/23/2021

Submitted Date:

11/23/2021

Document Number:

699803786

FIELD INSPECTION FORM

Loc ID 335145 Inspector Name: De Paolo, Corey On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: PO BOX 370
City: PARACHUTE State: CO Zip: 81635

Findings:

- 21 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257874	WELL	PR	08/21/2000	GW	045-07608	BARRETT GM 23-36	PR
292351	WELL	PR	09/20/2007	GW	045-14694	WILLIAMS GM 413-36	PR
292352	WELL	PR	07/01/2021	DSPW	045-14693	Williams GM 239-36	PR
292354	WELL	PR	10/01/2018	GW	045-14691	WILLIAMS GM 423-36	PR

General Comment:

COGCC Inspection Report Summary
On Monday 11/22/21 at approximately 13:00 hours, I, Inspector Corey De Paolo, Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC BARRETT66S96W /36NESW, Location #335145 in Garfield County Colorado.
Refer to document #699803446 inspection conducted on 7/22/21. Previous corrective actions have been completed. While there, I observed normal production operations.
During this inspection the following compliance issues were observed:

- 1) Wellhead signs weathered and not legible with a previous corrective action date of 9/22/21.
- 2) No battery sign located at the tank battery with a previous corrective action date of 9/22/21.
- 3) Location lacks stabilization. Insufficient tracking BMP with a previous corrective action date of 8/6/21.

- Location is located in a high priority habitat area. All drainages contribute to the Colorado river.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	No battery sign located at the tank battery.		
Corrective Action:	A permanent, conspicuous sign will be located at the tank battery.	Date:	09/22/2021
Type	OTHER		
Comment:	Horizontal separator units include an attached storage tank. Storage tank is approximately 2'x3'x14' with an approximate capacity of 15 barrels. Based on the sight glass the storage tank appears to be full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Wellhead sign weathered and not legible.		
Corrective Action:	Operators will ensure that signs are well maintained and legible, and will replace damaged signs.	Date:	09/22/2021

Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:		Date:	

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 5		
Comment:			

Corrective Action:		Date:	
Type: Plunger Lift	# 4		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Gas Meter Run	# 4		
Comment:	All meter runs have been calibrated in the last year.		
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	Injection well		
Corrective Action:		Date:	
Type: Bradenhead	# 4		
Comment:	No form of pressure monitoring equipment located on braden heads. All braden head valves are accessible.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	80 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	<u>257874</u>	Type:	<u>WELL</u>	API Number:	<u>045-07608</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>292351</u>	Type:	<u>WELL</u>	API Number:	<u>045-14694</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>292352</u>	Type:	<u>WELL</u>	API Number:	<u>045-14693</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>292354</u>	Type:	<u>WELL</u>	API Number:	<u>045-14691</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
		Gravel				
		Sediment Traps				
Gravel	Fail					Gravel insufficient
Berms						
		Compaction				
Other	Fail					Insufficient tracking BMP
Compaction	Fail					Location lacks stabilization
Sediment Traps						
Ditches						
		Berms				

Comment: [Location lacks stabilization. Insufficient tracking BMP.](#)

Corrective Action: [Oil and gas operators shall implement and maintain Best Management Practices \(BMPs\) at all oil and gas locations](#)

Date: 08/06/2021

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Refer to Sign/Markers and storm water for corrective actions.	depaoloc	11/23/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402879185	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5588676
699803787	Photos for Insp. #699803786	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5588670