

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/23/2021

Submitted Date:

11/29/2021

Document Number:

700703587**FIELD INSPECTION FORM**Loc ID 315986 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 200502Name of Operator: 31 OPERATINGAddress: 3021 RIDGE RD #156City: ROCKWALL State: TX Zip: 75032**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**9 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Thomson, Bud		BLThomps@BLM.gov	
, COGCC		mike.leonard@state.co.us	
, COGCC		kelly.rosenberg@state.co.us	<a href="#">regulatory/hearings</a>
operating, 31		kfreeman@31operating.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
231858	WELL	SI	09/01/2016	GW	103-09529	FEDERAL 33-4-B	SI

**General Comment:**[COGCC Inspection Report Summary](#)

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

On Tuesday 11/23/2021 at approximately 1400, I, Inspector Scott Ramsey, conducted a routine inspection at 31 Operating Federal 33-4-B, at Location # 315986 in Rio Blanco county Colorado.

While there, I observed no production operations. Well is shut in. All meters have been not calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. There is no evidence of tracking pad at time of inspection.

During this inspection the following compliance issues were observed:

1. No evidence of tracking control BMP's.
2. Fill slope shows signs of lack of stabilization with sediment migration.
3. Sink hole on access road over culvert.
4. Access road shows signs of lack of stabilization/compaction.
5. Locations weeds have turned into debris throughout location.
6. No evidence of Braden head access.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	See stormwater		
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	1-800-209-9762/911	Date:	
Corrective Action:		Date:	

<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	Locations weeds have turned into debris throughout location.		
Corrective Action:	Remove all debris	Date:	12/31/2021

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Other	# 1		
Comment:	Well head not on plunger lift		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	No evidence of Braden head access.		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2)	Date:	12/31/2021

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>		
Type		

Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 231858 Type: WELL API Number: 103-09529 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Last produced 8/2016. No MIT on file.Corrective Action: A Sundry Notice, Form 4, shall be submitted annually stating the method the well is Closed to the atmosphere and plans for future operation.Date: 12/31/2021

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail					
		Compaction	Fail			
		Culverts				

Comment: 1. No evidence of tracking control BMP's.  
 2. Fill slope shows signs of lack of stabilization with sediment migration.  
 3. Sink hole on access road over culvert.  
 4. Access road shows signs of lack of stabilization/compaction.

Corrective Action: Provide proof of tracking control BMP's and Install or repair required BMPs

Date: 12/31/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402881850	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5591166">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5591166</a>
700703594	Photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5591153">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5591153</a>