

# Inspection Photos

Loc ID: 321098

Operator: INVESTMENT EQUIPMENT LLC

Inspection Date: 11/30/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

ID: 321098 | Date: 11/30/2021

## Inspection Photos



**Photo 1.** Drone aerial photo facing west toward the [TANNER SEC REC UNIT #501](#) well site and production facility. The abandoned facility and well site has not been reclaimed and equipment remains.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 321098 | Date: 11/30/2021



## Inspection Photos



11.30.2021

**Photo 2.** Facing southwest toward the abandoned facility and well site which is approximately 3 acres in size.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 321098 | Date: 11/30/2021

## Inspection Photos



**Photo 3.** There is a soil material pile that remains at the north side of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 321098 | Date: 11/30/2021



## Inspection Photos



**Photo 4.** The electric powerline utilities remain at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 321098 | Date: 11/30/2021

## Inspection Photos



**Photo 5.** There is a metal shed that remains at the west side of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 321098 | Date: 11/30/2021



## Inspection Photos



**Photo 6.** Another soil material pile that remains at the south side of the location. There is a steel tank that remains.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 321098 | Date: 11/30/2021

## Inspection Photos



**Photo 7.** East side of the location facing southwest.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 321098 | Date: 11/30/2021