

Inspection Photos
Location Name: Montoya 10-2
Location ID: 326289



Photo 1 meter house



Photo 2 WH. Gravel piles blocking access to well head.

Inspection Photos
Location Name: Montoya 10-2
Location ID: 326289




Photo 3 Mechanical issue and stained soil



Photo 4 all signs have come off tank and are laying on ground.

Inspection Photos
Location Name: Montoya 10-2
Location ID: 326289



Photo 5 Access blocked to well head



Photo 6 Only open side to well head.

Inspection Photos
Location Name: Montoya 10-2
Location ID: 326289



Photo 7 Well sign buried by gravel pile.