

FORM  
INSPRev  
X/20

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/07/2021

Submitted Date:

12/07/2021

Document Number:

693506050

### FIELD INSPECTION FORM

Loc ID 326289 Inspector Name: Silver, Randy On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10663  
Name of Operator: ENDURING RESOURCES LLC  
Address: 6300 S SYRACUSE WAY, SUITE 525  
City: CENTENNIAL State: CO Zip: 80111

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 9 Number of Comments  
5 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Huntington, Heather		hhuntington@enduringresources.com	All Inspections per email 8/13/2021
Walter, Kyle		kwalter@enduringresources.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216179	WELL	PR	08/27/1991	GW	067-07785	MONTOYA 10-2	PR

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Sign or label not posted or information inaccurate on tanks or containers or sign/label too small to read at distance or installed in place where not visible.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	01/07/2022
Type	WELLHEAD		
Comment:	Well sign burried buy gravel cannot see entire sign.		
Corrective Action:	Comply with rule 605	Date:	01/07/2022

**Emergency Contact Number:**

Comment:	<input type="text"/>	Date:	<input type="text"/>
Corrective Action:	<input type="text"/>		

**Good Housekeeping:**

Type	OTHER		
Comment:	Stained soil: around well head		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 906	Date:	01/07/2022
Type	OTHER		
Comment:	Access: Well head is not accessable Surrounded by piles of gravel possible unsafe condition		
Corrective Action:	Comply with rule 602	Date:	01/07/2022
Type	OTHER		
Comment:	Mechanical issue: Electric HYD pump on well head appears to be leaking fluid.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.	Date:	01/07/2022

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:


Multiple Spills and Releases?

**Venting:**

Yes/No	NO		
Comment:	<input type="text"/>		
Corrective Action:		Date:	<input type="text"/>

**Flaring:**

Type			
Comment:	<input type="text"/>		
Corrective Action:		Date:	<input type="text"/>



**Inspected Facilities**Facility ID: 216179 Type: WELL API Number: 067-07785 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 04/01/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p><a href="#">COGCC Inspection Report Summary</a>  On Tuesday December 7, 2021 at approximately 1:29PM I Inspector Randy Silver, conducted an on-site inspection.  Location: Montoya #10-2  Operator: Enduring resources  API#: 067-07785  Loc ID: 326289  County: LaPlata  While there, I observed a producing well site  During this inspection the following possible compliance issues were observed:  Mechanical issue: Rule 608 e Corrective action date of 1-7-22 See photo 3  Stained soil: Rule 906 Corrective action date of 1-7-22 See photo 3  Well sign: Rule 605 Corrective action date of 1-7-22 See photo 7  Tanks signs: Rule 605 h Corrective action date of 1-7-22 see photo 4  Well access: Rule 602 Corrective action date of 1-7-22 See photos 2,5,6,7  This Well site is located in an active cement/ gravel facility.  Weather conditions: Cloudy  A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.  This is a summary of inspection report.</p>	silverr	12/07/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693506051	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5600529">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5600529</a>