

Inspection Photos

Location Name: CAERUS PICEANCE LLC G. JONES-67S96W /35SESE

Location ID: 334355



Photo #6151 from entrance to location.



Photo #6152 from entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC G. JONES-67S96W /35SESE

Location ID: 334355



Photo #6153 Location lacks stabilization.



Photo #6154 Location lacks stabilization.

Inspection Photos

Location Name: CAERUS PICEANCE LLC G. JONES-67S96W /35SESE

Location ID: 334355



Photo #6155 Insufficient tracking controls at entrance to location.