

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/14/2022

Submitted Date:

03/15/2022

Document Number:

699804250

**FIELD INSPECTION FORM**

Loc ID 334355 Inspector Name: De Paolo, Corey On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10456  
Name of Operator: CAERUS PICEANCE LLC  
Address: 1001 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

**Findings:**

- 21 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290608	WELL	PR	05/08/2008	GW	045-14159	G. JONES 35-44B	PR
290609	WELL	PR	09/01/2020	GW	045-14158	G. JONES 35-44A	PR
290610	WELL	PR	01/29/2013	GW	045-14157	G. JONES 35-34A	PR
290671	WELL	SI	12/01/2019	GW	045-14169	HELEY 35-44C	SI
290672	WELL	PR	01/07/2011	GW	045-14168	HELEY 35-34D	PR
290673	WELL	PR	04/25/2008	GW	045-14167	HELEY 35-34C	PR
290674	WELL	PR	05/12/2008	GW	045-14166	HELEY 35-44D	PR
291294	WELL	PR	01/29/2013	GW	045-14324	G. JONES 35-34B	PR

**General Comment:**

COGCC Inspection Report Summary  
On Friday 3/11/22 at approximately 13:00 hours, I, Inspector Corey De Paolo, Conducted a follow up inspection at CAERUS PICEANCE LLC G. JONES-67S96W /35SESE, Location #334355 in Garfield County Colorado.  
Refer to document #699804001 inspection conducted on 1/13/22.  
While there, I observed normal production operations.  
During this inspection the following compliance issues were observed:

- 1) Location lacks stabilization. Insufficient tracking BMP at entrance to location with a corrective action date of 3/26/22.
- Location is located in a high priority habitat area.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.  
This is a summary of inspection report.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include an attached storage tank. The storage tank is approximately 2'x3'x14' with an approximate capacity of 15 bbl. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	

<b>Equipment:</b>		corrective date
Type: Horizontal Heated Separator	# 8	
Comment:		
Corrective Action:		Date:

Type: Bradenhead	# 8	
Comment:	Pressure transducers located on braden head. All braden head valves are accessible	
Corrective Action:		Date:
Type: Plunger Lift	# 8	
Comment:	All wells on plunge lift	
Corrective Action:		Date:
Type: Gas Meter Run	# 8	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 4	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	290608	Type:	WELL	API Number:	045-14159	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:				Date:					
Facility ID:	290609	Type:	WELL	API Number:	045-14158	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:				Date:					
Facility ID:	290610	Type:	WELL	API Number:	045-14157	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:				Date:					
Facility ID:	290671	Type:	WELL	API Number:	045-14169	Status:	SI	Insp. Status:	SI
<b>Idle Well</b>									
Purpose:	<input checked="" type="checkbox"/> Shut In		<input type="checkbox"/> Temporarily Abandoned		Reminder: _____				
Comment:	Last produced November 2021								
Corrective Action:				Date:	_____				
Facility ID:	290672	Type:	WELL	API Number:	045-14168	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:				Date:					
Facility ID:	290673	Type:	WELL	API Number:	045-14167	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:				Date:					
Facility ID:	290674	Type:	WELL	API Number:	045-14166	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:				Date:					
Facility ID:	291294	Type:	WELL	API Number:	045-14324	Status:	PR	Insp. Status:	PR

**Producing Well**

Comment: Producing

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Fail					Gravel insufficient
		Compaction				
		Culverts				
Sediment Traps						
Ditches						
		Gravel				
Compaction	Fail					Location lacks stabilization
		Berms				
Berms						
		Sediment Traps				
		Ditches				
Other	Fail					Insufficient tracking BMP at entrance to location

Comment: [Location lacks stabilization. Insufficient tracking BMP at entrance to location.](#)

Corrective Action: [Oil and gas operators shall implement and maintain Best Management Practices \(BMPs\) at all oil and gas locations](#)

Date: 03/26/2022

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<a href="#">Refer to Storm water for corrective actions.</a>	depaoloc	03/14/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699804251	Photos for Insp. #699804250	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5693998">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5693998</a>