

Inspection Photos

API: 055-06101

Operator: MANZANO LLC

Inspection Date: 4/6/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06101 | Date: 4/6/2022

Inspection Photos



Photo 1. Drone aerial photo facing southwest along the access road. A pipe riser remains at the red arrow. The access road has not been reclaimed and the location is shown at the yellow arrow.



Photo 2. Close up view of the pipeline riser found along the access road. Pipeline riser has not been abandoned per 1100 Rules.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06101 | Date: 4/6/2022

Inspection Photos



Photo 3. Drone aerial photo facing southwest along the access road. There is erosion occurring along the road which has not been repaired and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06101 | Date: 4/6/2022

Inspection Photos



Photo 4. Drone aerial photo facing northwest along the access road. The access road has not been recontored and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06101 | Date: 4/6/2022

Inspection Photos



Photo 5. Drone aerial photo facing northwest shows the location has not been recontoured and reclaimed. The location disturbance is approximately 3.3 acres.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06101 | Date: 4/6/2022

Inspection Photos



Photo 6. The pipeline risers still remain at the location shown at red arrows. Pipeline riser should have been abandoned per 1100 Rules.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06101 | Date: 4/6/2022

Inspection Photos



Photo 7. Facing southwest overlooking the location. There are multiple areas of significant gully erosion along the cut and fill slopes shown at red arrows.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06101 | Date: 4/6/2022

Inspection Photos



Photo 8. The pit was never backfilled and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06101 | Date: 4/6/2022

Inspection Photos



Photo 9. This photo shows the significant erosion along the cut slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06101 | Date: 4/6/2022

Inspection Photos



Photo 10. Facing southeast toward the location. The location disturbance is approximately 3.3 acres.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06101 | Date: 4/6/2022