

Inspection Photos

API: 073-06736

Operator: MURFIN DRILLING COMPANY

Inspection Date: 5/16/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06736 | Date: 5/16/2022

Inspection Photos



Photo 1. Facing east along the former access road. There are some establishment of vegetation however, the vegetation does not appear to be progressing.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06736 | Date: 5/16/2022

Inspection Photos



Photo 2. The former road turns to the north. There are some establishment of vegetation however, the vegetation does not appear to be progressing.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06736 | Date: 5/16/2022

Inspection Photos



Photo 3. Facing north toward the fenced location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06736 | Date: 5/16/2022

Inspection Photos



Photo 4. Center of the location facing north. The desirable vegetation does not appear to be progressing. There is mostly undesirable weeds which appear to have been mowed for control.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06736 | Date: 5/16/2022

Inspection Photos



Photo 5. Center of the location facing west. The desirable vegetation does not appear to be progressing. There is mostly undesirable weeds which appear to have been mowed for control.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06736 | Date: 5/16/2022

Inspection Photos



Photo 6. Center of the location facing south. The desirable vegetation does not appear to be progressing. There is mostly undesirable weeds which appear to have been mowed for control.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06736 | Date: 5/16/2022

Inspection Photos



Photo 7. Center of the location facing east. The desirable vegetation does not appear to be progressing. There is mostly undesirable weeds which appear to have been mowed for control.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06736 | Date: 5/16/2022

Inspection Photos



Photo 8. View of groundcover shows mostly undesirable weeds (Kochia sp.). The location will need to be reseeded and weeds controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06736 | Date: 5/16/2022

Inspection Photos



Photo 9. Facing northeast. There is some desirable vegetation in the northeast portion of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06736 | Date: 5/16/2022

Inspection Photos



Photo 10. Facing toward the surrounding reference area consisting of Blue grama, Sand dropseed, among other species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06736 | Date: 5/16/2022