

Inspection Photos  
Location Name:UPRR 23 Pan Am D#1  
Location ID:319690



Photo#1 Production Tank



Photo#2 Separator

Inspection Photos  
Location Name:UPRR 23 Pan Am D#1  
Location ID:319690



Photo#3 Stained Soil



Photo#4 Produced Water Concrete Vault





Inspection Photos  
Location Name:UPRR 23 Pan Am D#1  
Location ID:319690



Photo#5 Potential pinhole in production tank. Stained Soil



Photo#6 PumpJack