

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/02/2022

Submitted Date:

06/03/2022

Document Number:

702500070

FIELD INSPECTION FORM

Loc ID 325619 Inspector Name: Klink, Alex On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 96735
Name of Operator: WILLIFORD RESOURCES, L.L.C.
Address: 6506 S LEWIS AVE STE 102
City: TULSA State: OK Zip: 74136

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 16 Number of Comments
- 7 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Stevens, Glenn	(970) 749-0192	glennstevens@centurylink.net	All SW field inspections
Williford, Hearne		hwilli@swbell.net	All SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215114	WELL	PR	02/01/2020	OW	067-06719	M & M 6	PR

General Comment:

[Inspectors Alex Klink and Steve Labowskie on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.](#)

Location			
Lease Road:			
Type	Access		
comment:	Dirt access road		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Well sign is posted behind fence panel and not legible.		
Corrective Action:	Install sign to comply with rule 605.g		Date: <u>07/02/2022</u>
Type	TANK LABELS/PLACARDS		
Comment:	Crude Oil tank placard is deteriorated.		
Corrective Action:	Install sign to comply with Rule 605.e.		Date: <u>07/02/2022</u>
Emergency Contact Number:			
Comment:	Emergency numbers listed: 918-712-8828 and 911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Fence panel is not in use (IMG 13).		
Corrective Action:	Use or remove unused equipment per rule 606.		Date: <u>06/17/2022</u>
Type	DEBRIS		
Comment:	Thread protectors (IMG 11) and steel cable (IMG 12) present on location.		
Corrective Action:	Remove debris to comply with rule 606.		Date: <u>06/17/2022</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	OTHER		
Comment:	Pump jack is enclosed on 3 sides by steel pipe fencing.		
Corrective Action:			Date:
Equipment:			
Type: Deadman # & Marked	# 4		corrective date
Comment:	4 rig anchors, one rig anchor is unmarked.		
Corrective Action:	Install proper guy line markers per Rule 1003.a		Date: <u>06/16/2022</u>
Type: Bradenhead	# 1		
Comment:	Bradenhead is accessible.		

Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	2" line from wellhead to tank battery.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		37.138011,-108.103060
Comment:	Crude oil tank paint has deteriorated (IMG 06).				
Corrective Action:	Paint tank per rule 425.				Date: 09/02/2022

Paint

Condition	Inadequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	Maintenance required due to animal burrows (IMG 09).			
Corrective Action:	Repair berms or other secondary containment devices. Since this facility does not require major modification it falls under the old Rule 605a.(4)			Date: 07/02/2022

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 215114 Type: WELL API Number: 067-06719 Status: PR Insp. Status: PR

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No observed impact of storm water. Storm water controls seem sufficient at time of report.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500072	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5770516