

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/17/2022

Submitted Date:

06/20/2022

Document Number:

702500105

FIELD INSPECTION FORM

Loc ID 312096 Inspector Name: Klink, Alex On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 16 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, General		FarmingtonRegulatoryTechs@hilcorp.com	All SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259853	WELL	PR	10/23/2008	CBM	067-08427	HAYES 33-9 5-3	PR
293346	WELL	PR	02/01/2011	CBM	067-09429	HAYES 33-9 5-3A	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

Equipment and vehicles associated with the landowner are present along the perimeter of this location.

Location			
Lease Road:			
Type	Main		
comment:	Gravel main road.		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Produced water tank label is deteriorated and not legible (IMG 09).		
Corrective Action:	Install sign to comply with Rule 605.h.		Date: 08/17/2022
Emergency Contact Number:			
Comment:	Emergency contact listed on well sign.		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	STORAGE OF SUPL		
Comment:	Equipment and supplies stored near Hayes 33-9 5-3 wellhead (IMG 04).		
Corrective Action:	Remove equipment per rule 606.		Date: 07/03/2022
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment near produced water tank (IMG 07 and IMG 08).		
Corrective Action:	Use or remove equipment per rule 606.		Date: 07/03/2022
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Pump jacks enclosed by steel fencing		
Corrective Action:			Date:
Type	OTHER		
Comment:	Separation equipment, produced water tank, and gas meter run are enclosed by stock panel.		
Corrective Action:			Date:
Equipment:			
Type: Vertical Heated Separator	# 2		corrective date
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 1		
Comment:	Rig anchor not marked (IMG 06).		

Corrective Action:	Install proper guy line markers per Rule 1003.a	Date:	07/03/2022
Type: Prime Mover	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:	Separator vent stack and produced water tank vent are screened properly.		
Corrective Action:		Date:	
Type: Pump Jack	# 2		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 8		
Comment:	3" line, 4" line and 2" line coming from wellhead at each pump jack, line from separator equipment to produced water, 3" line from separator to gas meter run.		
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	Bradenheads are accessible.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		37.129164,-107.853898
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	285 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	
--------	--

Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 259853 Type: WELL API Number: 067-08427 Status: PR Insp. Status: PR

Producing Well

Comment: Truck parked within 100' of Hayes 33-9 5-3 pump jack (IMG 05)

Corrective Action: Ensure vehicles not necessary for operations are parked a minimum of 100' of wellhead per rule 602.k.

Date: 06/23/2022

Facility ID: 293346 Type: WELL API Number: 067-09429 Status: PR Insp. Status: PR

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Gravel	Pass					

Comment: No observed impact of storm water. Storm water controls seem sufficient at time of report.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403083653	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5783452
702500106	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5783450